

SUPPLY HEADER PROJECT ENVIRONMENTAL SURVEY

Waterbody Datasheets and Photo Pages

TL-635

Tyler County

West Virginia

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT TO Indian Creek		Waterbody ID: STYG001	Date: 4-30-15
State: WV	County: Tyler	Company: DAWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 32-001-C002		Milepost Entry: 22.6	Milepost Exit: 22.6	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM

Width: 5 ft.

Height: 1 ft.

OHWM Indicator: (check all that apply) ☐ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 10 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline: 40 ft.

Depth of Water at Centerline: (Approx.) 0 ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) < 1 fps

Bank height Right: 3 ft. Left: 3 ft.

Bank slope Right: 60 degrees Left: 60 degrees

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 60 % 35 % 3 % 2 % _____ %

Width of Riparian Zone: > 100 ft.

Vegetative Layers: (check all that apply) ☒ Trees: ☒ Shrubs: ☒ Herbs: ☒

Avg. DBH of Dominants: _____ in. _____ in.

Dominant Bank Vegetation: (list) Quercus rubra, Carpinus caroliniana, Rosa multiflora, Polystrum acrostoides

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) riffles

Aquatic Organisms Observed: (list) NONE

Invasive and/or T&E Species Observed: (list) Rosa multiflora

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: NONE

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



styg001



Waterbody *styg001* facing upstream



Waterbody *styg001* facing downstream

Styg001



Waterbody styg001 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DT Supply Hender Waterbody Name: Indian Creek Waterbody ID: STY6002 Date: 4/30/15

State: WV County: Tyler Company: DDWEST Crew Member Initials: JD, JG Photo ID(s):

Tract Number(s): 32-001-C002 Milepost Entry: 2.7 Milepost Exit: 2.7 Associated Wetland ID(s): NONE

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale^a ☐ Other:

OHWM Width: 15 ft. Height: ft. OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 18 ft. Width of Waterbody - Water Edge to Water Edge at Centerline: 6 ft. Depth of Water at Centerline: (Approx.) 2" ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering Water velocity: (Approx.) 72 fps Bank height Right: 2 ft. Left: 2 ft. Bank slope Right: 50 degrees Left: 70 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 20 % 60 % 10 % 10 % % %

Width of Riparian Zone: 20 ft. Vegetative Layers: (check all that apply) ☒ Trees: in. ☒ Shrubs: in. ☒ Herbs Avg. DBH of Dominants: (approx.) in.

Dominant Bank Vegetation: (list) Quercus rubra, Carpinus caroliniana, Polystichum acrostoides, Rosa multiflora

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) rifle, pools, overhanging vegetation

Aquatic Organisms Observed: (list) small invertebrates

Invasive and/or T&E Species Observed: (list) Rosa multiflora

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

STY6002

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



styg002



Waterbody *styg002* facing upstream



Waterbody *styg002* facing downstream

styg002



Waterbody styg002 facing upline cross stream

SUPPLY HEADER PROJECT ENVIRONMENTAL SURVEY

Waterbody Datasheets and Photo Pages

TL-635

Wetzel County

West Virginia

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header Waterbody Name: UNT TO Buffalo Run Waterbody ID: SWZ6024 Date: 5-13-15

State: WV County: Wetzel Company: DAWEST Crew Member Initials: JD, JG Photo ID(s):

Tract Number(s): 33-001-A002 Milepost Entry: 24.3 Milepost Exit: 24.3 Associated Wetland ID(s): WWZ6003 f w

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 15 ft. Height: 6 ft. OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 20 ft. Width of Waterbody - Water Edge to Water Edge at Centerline: ft. Depth of Water at Centerline: (Approx.) ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering Water velocity: (Approx.) < 1 fps Bank height Right: 3 ft. Left: 2 ft. Bank slope Right: 30 degrees Left: 15 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 10 % 60 % 10 % 20 % % %

Width of Riparian Zone: ft. Vegetative Layers: (check all that apply) ☒ Trees: 10 in. ☒ Shrubs: in. ☒ Herbs Avg. DBH of Dominants: (approx.) 10 in.

Dominant Bank Vegetation: (list) Acer barbatum, Platanus occidentalis, Fagus grandifolia, Athyrrium, Felix-Simile

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Pools, riffles

Aquatic Organisms Observed: (list) small frogs + small fish

Invasive and/or T&E Species Observed: (list) None

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: NONE

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ6024

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg024



Waterbody swzg024 facing upstream



Waterbody swzg024 facing downstream

Swzg024



Waterbody swzg024 facing upline cross stream

Waterbody Data Sheet

Survey Description					
Project Name: <u>Supply Wender</u>		Waterbody Name: <u>UNT. TO SOONHODS BUFFALORUN</u>		Waterbody ID: <u>SWZH025</u>	Date: <u>7-24-18</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>ID, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					
Physical Attributes					
Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: <u>8</u> ft. Height: <u>4"</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>12</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>0</u> ft.		Depth of Water at Centerline: (Approx.) <u>0</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>1 1/2</u> ft. Left: <u>2</u> ft. Bank slope Right: <u>30</u> degrees Left: <u>30</u> degrees	
Qualitative Attributes					
Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: _____ % <u>20</u> % <u>10</u> % <u>20</u> % _____ % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Dominant Bank Vegetation: (list) <u>Liriodendron tulipifera, Platanus occidentalis, Carpinus caroliniana, Microsagium viminalis</u>					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>pools</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>Microsagium viminalis</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>NONE</u>					
Stream Quality ^B : (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SW24025

* Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh025



Waterbody swzh025 facing upstream



Waterbody swzh025 facing downstream

Swzh025



Waterbody swzh025 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO Buffalo Run</u>		Waterbody ID: <u>SW2H023</u>	Date: <u>7-24-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:
(check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial	
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____	
OHWM Width: <u>15</u> ft. Height: _____ ft.	OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>25</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>6</u> ft.
Depth of Water at Centerline: (Approx.) <u>6</u> ft.	

Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) <u><3</u> fps	Bank height Right: <u>4</u> ft. Left: <u>6</u> ft.	Bank slope Right: <u>30</u> degrees Left: <u>70</u> degrees
--	---	--	---

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____	
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____	
% of Substrate: _____ % <u>70</u> % <u>10</u> % <u>20</u> % _____ %	
Width of Riparian Zone: <u>750</u> ft.	Vegetative Layers: (check all that apply) ☒ Trees: <u>12</u> in. ☒ Shrubs: _____ in. ☒ Herbs

Dominant Bank Vegetation:
(list) Platanus occidentalis, Rosa multiflora, Microstegium vimineum

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):
(list) Pools, Riffles, overhanging banks & veg.

Aquatic Organisms Observed:
(list) Small fish, frogs, invertebrates

Invasive and/or T&E Species Observed:
(list) Rosa multiflora, Microstegium vimineum

Tributary is:
(check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances:
(check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Access road two 24" culvert

Stream Quality:
(check one) ☐ High ☒ Moderate ☐ Low Pipes

Waterbody ID:

SW2 H023

° Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

° High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh023



Waterbody swzh023 facing upstream



Waterbody swzh023 facing downstream

Swzh023



Waterbody swzh023 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNTTD BUFFALO RUN</u>		Waterbody ID: <u>SWZH024</u>	Date: <u>7-24-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: <u>4</u> ft. Height: <u>6</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested Vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>16</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>10</u> ft.		Depth of Water at Centerline: (Approx.) <u>1</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>1</u> <u>< 2</u> fps		Bank height Right: <u>3</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>90</u> degrees Left: <u>20</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☒ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>15</u> % <u>75</u> % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>12</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Liriodendron tulipifera, Platanus occidentalis, Carpinus caroliniana, Microstegium vimineum</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles, Pools, overhanging banks + veg</u>					
Aquatic Organisms Observed: (list) <u>small fish, frogs, invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>Microstegium vimineum</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>the dam</u>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SW24024

* **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

° **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh024



Waterbody swzh024 facing upstream



Waterbody swzh024 facing downstream

Swzh024



Waterbody swzh024 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Station</u>	Waterbody Name: <u>UNT TO BUFFALO RUN</u>	Waterbody ID: <u>SW24022</u>	Date: <u>7-24-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>SD, PP</u>
Tract Number(s): <u>33-001-A002</u>	Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>

Survey Type:
(check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial		
Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____		
OHWM Width: <u>3</u> ft. Height: <u>6</u> ft.	OHWM Indicator: (check all that apply) ☐ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☒ Abrupt plant community change ☐ Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.	Depth of Water at Centerline: (Approx.) <u>2</u> ft.

Sinuosity: (check one) ☒ Straight ☐ Meandering	Water velocity: (Approx.) <u><1</u> fps	Bank height Right: <u>2</u> ft. Left: <u>2</u> ft.	Bank slope Right: <u>30</u> degrees Left: <u>30</u> degrees
--	---	--	---

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☒ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____	
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____	
% of Substrate: _____ % <u>20</u> % <u>20</u> % <u>60</u> % _____ %	
Width of Riparian Zone: <u>0</u> ft.	Vegetative Layers: (check all that apply) ☐ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs
Avg. DBH of Dominants: (approx.) _____ in.	

Dominant Bank Vegetation:
(n/a) Microstegium vimineum, Salix nigra, Typha angustifolia, Juncus coriaceus

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(n/a) Ponds

Aquatic Organisms Observed:
(n/a) Small invertebrates, and frogs

Invasive and/or T&E Species Observed:
(n/a) Microstegium vimineum

Tributary is:
(check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances:
(check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent road + gas line yard.

Stream Quality:
(check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SW24022

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh022



Waterbody swzh022 facing upstream



Waterbody swzh022 facing downstream

Swzh022



Waterbody swzh022 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO Buffalo Run</u>		Waterbody ID: <u>SW2 H026</u>	Date: <u>7-24-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>LDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:
(check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification:
(check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type:
(check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale* ☐ Other: _____

OHWM
Width: 3 ft.
Height: 6" ft.

OHWM Indicator:
(check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 5 ft.
Width of Waterbody - Water Edge to Water Edge at Centerline: 1 ft.
Depth of Water at Centerline: (Approx.) 1 ft.

Sinuosity:
(check one) ☒ Straight ☐ Meandering

Water velocity:
(Approx.) <1 fps

Bank height
Right: 6 ft.
Left: 6 ft.

Bank slope
Right: 60 degrees
Left: 60 degrees

Qualitative Attributes

Water Appearance:
(check one) ☐ No water ☐ Clear ☒ Turbid ☒ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate:
(check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: _____ % 20 % 20 % 60 % _____ % _____ %

Width of Riparian Zone: 0 ft.

Vegetative Layers:
(check all that apply) ☐ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation:
(list) Viburnum dentatum, Microstegium vimineum, Impatiens capensis Rosa multi. flora

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list) Pools

Aquatic Organisms Observed:

(list) Invertebrates

Invasive and/or T&E Species Observed:

(list) Microstegium vimineum Rosa multi. flora

Tributary is:
(check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances:
(check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: Adjacent Road

Stream Quality^b:
(check one) ☐ High ☒ Moderate ☐ Low

Culvert Pipe

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh026



Waterbody swzh026 facing upstream



Waterbody swzh026 facing downstream

Swzh026



Waterbody swzh026 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>	Waterbody Name: <u>UNT TO Buffalo Run</u>	Waterbody ID: <u>SW24012</u>	Date: <u>7-23-15</u>
State: <u>WI</u>	County: <u>WETZEL</u>	Company: <u>ADQUEST</u>	Crew Member Initials: <u>JD, PP</u>
Tract Number(s): <u>33-001-1A002</u>	Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____

OHWM
Width: 6 ft.
Height: 3" ft.

OHWM Indicator: (check all that apply)
☐ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft.
 Width of Waterbody - Water Edge to Water Edge at Centerline: 1 ft.
 Depth of Water at Centerline: (Approx.) 1/4" ft.

Sinuosity: (check one) ☒ Straight ☐ Meandering

Water velocity: (Approx.) <1 fps

Bank height
Right: 1 ft.
Left: 1 ft.

Bank slope
Right: 80 degrees
Left: 90 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 20 % 70 % _____ % 10 % _____ %

Width of Riparian Zone: 0 ft.

Vegetative Layers: (check all that apply)
☐ Trees: _____ in.
☒ Shrubs: _____ in.
☒ Herbs: _____ in.

Dominant Bank Vegetation: (list)
Impatiens capensis, Boehmeria cylindrica, Fagus grandifolia

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list)
R. Ayes

Aquatic Organisms Observed:

(list)
NONE

Invasive and/or T&E Species Observed:

(list)
Microstegium vimineum

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: roadside ditch

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZHO12

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh012



Waterbody swzh012 facing upstream



Waterbody swzh012 facing downstream

Swzh012



Waterbody swzh012 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Wender		Waterbody Name: UNT TO BUFFALO RUN		Waterbody ID: SW26025	Date: 5-13-15
State: WV	County: Wetzel	Company: DOWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-001-1A002		Milepost Entry: 24.9	Milepost Exit: 24.9	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other:					
OHWM Width: <u>4</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>8</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>2.5</u> ft.		Depth of Water at Centerline: (Approx.) <u>1</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>< 1</u> fps		Bank height Right: <u>1</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>20</u> degrees Left: <u>30</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>60</u> % <u>10</u> % <u>20</u> % _____ %					
Width of Riparian Zone: <u>725</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>10</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <i>Platanus occidentalis, Liriodendron tulipifera, Fraxinus pennsylvanica, Equisetum hyemale, Eulalia viminalis</i>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <i>riffles, pools</i>					
Aquatic Organisms Observed: (list) <i>small invertebrates, small frogs</i>					
Invasive and/or T&E Species Observed: (list) <i>Eulalia viminalis</i>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <i>Easement</i>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SW26025

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg025



Waterbody swzg025 facing upstream



Waterbody swzg025 facing downstream

Swzg025



Waterbody swzg025 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT TO Buffalo Run		Waterbody ID: SWZ6026	Date: 5-13-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-001-A002		Milepost Entry: 24.9	Milepost Exit: 24.9	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____

OHWM
Width: 12 ft.
Height: _____ ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining
☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 18 ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: 3 ft.	Depth of Water at Centerline: (Approx.) 2" ft.
Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) 41 fps	Bank height Right: 10 ft. Left: 12 ft.
		Bank slope Right: 70 degrees Left: 70 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 60 % 10 % 20 % _____ %

Width of Riparian Zone: 75 ft.

Vegetative Layers: (check all that apply) ☒ Trees: _____ ☒ Shrubs: _____ ☒ Herbs: _____

Avg. DBH of Dominants: (approx.) _____ in. _____ in.

Dominant Bank Vegetation: (list) *Phytolacca occidentalis, Fraxinus pensylvanica, Liriodendron tulipifera, Fagus grandifolia, Polystichum acrostoides*

Aquatic Habitats (exc. submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) *rock, pools*

Aquatic Organisms Observed: (list) *small invertebrates, small frogs*

Invasive and/or T&E Species Observed: (list) *Eubalia virens*

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: *erosion*

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ6026

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg026



Waterbody swzg026 facing upstream



Waterbody swzg026 facing downstream

Swzg026



Waterbody swzg026 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Headbox</u>		Waterbody Name: <u>UNT TO BUFFALO RUN</u>		Waterbody ID: <u>SWZH010</u>	Date: <u>7/23/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM
Width: 9 ft.
Height: 1 ft.

OHWM Indicator: (check all that apply)
☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 15 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.

Depth of Water at Centerline: (Approx.) _____ ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) < 2 fps

Bank height
Right: 1 1/2 ft.
Left: 1 1/2 ft.

Bank slope
Right: 20 degrees
Left: 45 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 70 % 5 % 15 % _____ % _____ %

Width of Riparian Zone: 725 ft. on one side

Vegetative Layers: (check all that apply) ☒ Trees: _____ ☒ Shrubs: _____ ☒ Herbs: _____

Avg. DBH of Dominants: (approx.) _____ in. _____ in.

Dominant Bank Vegetation: (list)
Phytolacca occidentalis, Juglans nigra, Carpinus, Microstegium vimineum

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list)
Riffles, Pools, Overhanging roots

Aquatic Organisms Observed: (list)
small invertebrates

Invasive and/or T&E Species Observed: (list)
Microstegium vimineum

Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Road

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ4010

* Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh010



Waterbody swzh010 facing upstream



Waterbody swzh010 facing downstream

Swzh010



Waterbody swzh010 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO BUFFALO RUN</u>		Waterbody ID: <u>SW2H011</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:
(check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial	
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____	
OHWM Width: <u>6</u> ft. Height: <u>8</u> ft.	OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>10</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>0</u> ft.
Depth of Water at Centerline: (Approx.) <u>1/4</u> ft.	

Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) <u><1</u> fps	Bank height Right: _____ ft. Left: _____ ft.	Bank slope Right: _____ degrees Left: _____ degrees
--	---	--	---

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____	
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____	
% of Substrate: <u>20</u> % <u>70</u> % <u>5</u> % <u>5</u> % _____ %	
Width of Riparian Zone: <u>725</u> ft.	Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs
Avg. DBH of Dominants: (approx.) _____ in.	

Dominant Bank Vegetation:
(list) Lindbueron tulipifera, Acer Barbatum, Fagus grandifolia, Boehmeria Microstegium, cylindrica

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):
(list) pools, riffles

Aquatic Organisms Observed:
(list) NONE

Invasive and/or T&E Species Observed:
(list) NONE Microstegium viminea

Tributary is:
(check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances:
(check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Road

Stream Quality:
(check one) ☐ High ☒ Moderate ☐ Low + culvert

Waterbody ID:

SWZH011

• **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

• **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh011



Waterbody swzh011 facing upstream



Waterbody swzh011 facing downstream

Swzh011



Waterbody swzh011 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT 70</u>		Waterbody ID: <u>SWZ H008</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>NO PARCEL ID NUMBER</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM
Width: 4 ft.
Height: 6" ft.

OHWM Indicator: (check all that apply)
☐ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>6</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.	Depth of Water at Centerline: (Approx.) _____ ft.
Sinuosity: (check one) ☒ Straight ☐ Meandering	Water velocity: (Approx.) <u>1</u> fps	Bank height Right: <u>4</u> ft. Left: <u>2</u> ft.
		Bank slope Right: <u>80</u> degrees Left: <u>60</u> degrees

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 70 % 70 % _____ % 10 % _____ % _____ %

Width of Riparian Zone: 0 ft.

Vegetative Layers: (check all that apply)
☒ Trees: 8 in. ☒ Shrubs: _____ in. ☒ Herbs: _____ in.
 Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation: (list)
Elaeagnus pungens, Linnaea borealis, Microstegium vimineum

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list)
Riffles

Aquatic Organisms Observed: (list)
NONE

Invasive and/or T&E Species Observed: (list)
Microstegium vimineum, Rosa multiflora

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: roadside ditch

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ H008

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh008



Waterbody swzh008 facing upstream



Waterbody swzh008 facing downstream

Swzh008



Waterbody swzh008 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Hauler</u>		Waterbody Name: <u>UNT TO</u>		Waterbody ID: <u>SWZ H009</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>NO PARCEL ID NUMBER</u>		Milepost Entry: <u>N/A</u>	Milepost Exit: <u>N/A</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:
(check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification:
(check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type:
(check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM
Width: 2 ft.
Height: 4" ft.

OHWM Indicator:
(check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>4</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> 2 ft.	Depth of Water at Centerline: (Approx.) <u>1/2"</u> ft.
Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) <u><1</u> fps	Bank height Right: <u>1</u> ft. Left: <u>1</u> ft.
		Bank slope Right: <u>60</u> degrees Left: <u>60</u> degrees

Qualitative Attributes

Water Appearance:
(check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate:
(check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 70 % _____ % 20 % _____ %

Width of Riparian Zone: 10 ft.

Vegetative Layers:
(check all that apply) ☒ Trees: 15 in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants:
(approx.) 15 in.

Dominant Bank Vegetation:
(list) Platanus occidentalis, Ulmus americana, Rosa multiflora, Microstegium vimineum

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):
(list) riffles

Aquatic Organisms Observed:
(list) NONE

Invasive and/or T&E Species Observed:
(list) Rosa multiflora, Microstegium vimineum

Tributary is:
(check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances:
(check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: ADJACENT FOREST

Stream Quality:
(check one) ☐ High ☒ Moderate ☐ Low ROAD

Waterbody ID:

SWZ H009

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh009



Waterbody swzh009 facing upstream



Waterbody swzh009 facing downstream

Swzh009



Waterbody swzh009 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: SUPPLY HEADCOR		Waterbody Name: UNT TO Arches Fork		Waterbody ID: SWZH013	Date: 7-23-15
State: WV	County: WETZEL	Company: DDWEST	Crew Member Initials: JD, PP	Photo ID(s):	
Tract Number(s): 33-001-A002		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____

OHWM
Width: **3** ft.
Height: **8"** ft.

OHWM Indicator: (check all that apply)
☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 5 ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.	Depth of Water at Centerline: (Approx.) _____ ft.
Sinuosity: (check one) ☒ Straight ☐ Meandering	Water velocity: (Approx.) < 1 fps	Bank height Right: 3 ft. Left: 1 ft.
		Bank slope Right: 80 degrees Left: 70 degrees

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply)
☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: **10** % **70** % **5** % **15** % _____ %

Width of Riparian Zone: **0** ft.

Vegetative Layers: (check all that apply)
☐ Trees: _____
☒ Shrubs: _____
☒ Herbs: _____
 Avg. DBH of Dominants: _____ in.

Dominant Bank Vegetation: (list)
~~Spartina patens~~ **Carpinus caroliniana, Microstegium vimineum**
Eragrostis canadensis

Aquatic Habitats (i.e. submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):
PODIS

Aquatic Organisms Observed: (list)
NONE

Invasive and/or T&E Species Observed: (list)
Microstegium vimineum

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply)
☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: **roadside ditch**

Stream Quality²: (check one) ☐ High ☒ Moderate ☐ Low

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh013



Waterbody swzh013 facing upstream



Waterbody swzh013 facing downstream

Swzh013



Waterbody swzh013 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Wacker</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SWZ4015</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM
Width: 8 ft.
Height: _____ ft.

OHWM Indicator: (check all that apply)
☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 10 ft.
 Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.
 Depth of Water at Centerline: (Approx.) _____ ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) < 2 fps

Bank height
Right: 5 ft.
Left: 4 ft.

Bank slope
Right: 80 degrees
Left: 80 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 30 % 60 % 5 % 15 % _____ %

Width of Riparian Zone: 725 ft.

Vegetative Layers: (check all that apply)
☒ Trees: 8 in. ☒ Shrubs: _____ in. ☒ Herbs
 Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation: (list)
Tilia americana, Hammelia virginica, Verbesina occidentalis

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):
 (list)
riffles, pools

Aquatic Organisms Observed: (list)
small invertebrates

Invasive and/or T&E Species Observed: (list)
Microsteira viminea

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Rd culvert pipe

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZH015

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh015



Waterbody swzh015 facing upstream



Waterbody swzh015 facing downstream

Swzh015



Waterbody swzh015 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT + Archer Fork</u>		Waterbody ID: <u>SWZ4016</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM Width: 6 ft.
Height: 4 ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline: 2 ft.

Depth of Water at Centerline: (Approx.) 2 ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) < 2 fps

Bank height Right: 2 ft. Left: 2 ft.

Bank slope Right: 70 degrees Left: 30 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: _____ % 70 % 10 % 20 % _____ %

Width of Riparian Zone: 725 ft.

Vegetative Layers: (check all that apply) ☒ Trees: _____ ☒ Shrubs: _____ ☒ Herbs: _____

Avg. DBH of Dominants: _____ in. _____ in.

Dominant Bank Vegetation: (list) Linodendron tulipifera, Polystrichum acrostichoides, Crataegus sp.

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) pools, riffles

Aquatic Organisms Observed: (list) small invertebrates

Invasive and/or T&E Species Observed: (list) Microstegium vimineum

Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Road

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ#016

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh016



Waterbody swzh016 facing upstream



Waterbody swzh016 facing downstream

Swzh016



Waterbody swzh016 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Head</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SW2H014</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM Width: 6 ft.
Height: 1 ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 10 ft.
Width of Waterbody - Water Edge to Water Edge at Centerline: 1 ft.
Depth of Water at Centerline: (Approx.) 1/2 ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) < 2 fps

Bank height Right: 2 ft. Left: 2 ft.

Bank slope Right: 35 degrees Left: 35 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 70 % 5 % 15 % _____ %

Width of Riparian Zone: 725 ft.

Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation: (list) Fagus grandifolia, Carpinus caroliniana, Polystichum acrostichoides

Aquatic Habitats (ex. submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Riffles, pools

Aquatic Organisms Observed: (list) Small invertebrates

Invasive and/or T&E Species Observed: (list) Microstegium vimineum

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: adjacent road

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZH014

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh014



Waterbody swzh014 facing upstream



Waterbody swzh014 facing downstream

Swzh014



Waterbody swzh014 facing upline cross stream

Survey Description				
Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SWZ H017</u>
State: <u>WV</u>		County: <u>WETZEL</u>	Company: <u>DAWEST</u>	Crew Member Initials: <u>JD, PP</u>
Date: <u>7-23-15</u>				
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>WWZH022eW</u>
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____				
Physical Attributes				
Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial				
Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____				
OHWM Width: <u>3</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.		Depth of Water at Centerline: (Approx.) <u>2"</u> ft.
Sinuosity: (check one) ☒ Straight ☐ Meandering		Water velocity: (Approx.) <u>< 1</u> fps		Bank height: Right: <u>1</u> ft. Left: <u>1</u> ft.
Bank slope: Right: <u>70</u> degrees Left: <u>70</u> degrees				
Qualitative Attributes				
Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____				
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____				
% of Substrate: _____ % <u>30</u> % <u>20</u> % <u>50</u> % _____ % _____ %				
Width of Riparian Zone: <u>0</u> ft.		Vegetative Layers: (check all that apply) ☐ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs		
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Liriodendron tulipifera, Microstegium vimineum</u>				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): <u>Pools</u>				
Aquatic Organisms Observed: (list) <u>Small invertebrates</u>				
Invasive and/or T&E Species Observed: (list) <u>Microstegium vimineum</u>				
Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated				
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent road</u>				
Stream Quality ^b : (check one) ☐ High ☐ Moderate ☐ Low				

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^bHigh Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh017



Waterbody swzh017 facing upstream



Waterbody swzh017 facing downstream

Swzh017



Waterbody swzh017 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Warden</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SWZH018</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A002</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 84 ft.
Height: 1 ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>6</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>0</u> ft.	Depth of Water at Centerline: (Approx.) <u>0</u> ft.
Sinuosity: (check one) ☒ Straight ☐ Meandering	Water velocity: (Approx.) <u><1</u> fps	Bank height Right: <u>3</u> ft. Left: <u>2</u> ft.
		Bank slope Right: <u>45</u> degrees Left: <u>30</u> degrees

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 10 % 70 % 5 % 15 % _____ %

Width of Riparian Zone: 725 one side ft.

Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation: (list) Platanus occidentalis, Lindera benzoin, Impatiens capensis, Polygonum virginicum

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list) pools,

Aquatic Organisms Observed: (list) small invertebrates

Invasive and/or T&E Species Observed: (list) Microstegium vimineum

Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Road

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZH018

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh018



Waterbody swzh018 facing upstream



Waterbody swzh018 facing downstream

Swzh018



Waterbody swzh018 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Headers</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SW240A</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A089</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other:					
OHWM Width: <u>8</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>10</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>2</u> ft.		Depth of Water at Centerline: (Approx.) _____ ft.	
Sinuosity: (check one) ☐ Straight ☐ Meandering		Water velocity: (Approx.) <u>< 1</u> fps		Bank height Right: <u>1</u> ft. Left: <u>1</u> ft.	
Bank slope Right: <u>20</u> degrees Left: <u>20</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>15</u> % <u>80</u> % _____ % <u>5</u> % _____ % _____ %					
Width of Riparian Zone: <u>225</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs Avg. DBH of Dominants: _____ in.			
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Robinia pseudoacacia, Impatiens capensis, Lindera microstegium viminea, bonzoin</u>					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles, pools</u>					
Aquatic Organisms Observed: (list) <u>Small invertebrates, small fish</u>					
Invasive and/or T&E Species Observed: (list) <u>Microstegium viminea</u>					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent Road & Culvert pipe</u>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SWZHD19

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

° High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh019



Waterbody swzh019 facing upstream



Waterbody swzh019 facing downstream

Swzh019



Waterbody swzh019 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Headcar</u>		Waterbody Name: <u>UNT TO Arches Fork</u>		Waterbody ID: <u>SW24020</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>No parcel number listed</u>		Milepost Entry: <u>N/A</u>	Milepost Exit: <u>N/A</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM Width: 8 ft. Height: 1 ft.

OHWM Indicator: (check all that apply) ☐ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 10 ft. Width of Waterbody - Water Edge to Water Edge at Centerline: 5 ft. Depth of Water at Centerline: (Approx.) 4" ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering Water velocity: (Approx.) < 2 fps Bank height Right: 2 ft. Left: 1 ft. Bank slope Right: 35 degrees Left: 20 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 60 % 10 % 20 % _____ %

Width of Riparian Zone: 725 ft. side Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants: (approx.) _____ in.

Dominant Bank Vegetation: (list) Platanus occidentalis, Lindera benzoin, Verbesina occidentalis

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list) Pools

Aquatic Organisms Observed: (list) Small fish, invertebrates

Invasive and/or T&E Species Observed: (list) Microstegium vimineum

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent road

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SW2H020

*Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^bHigh Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh020



Waterbody swzh020 facing upstream



Waterbody swzh020 facing downstream

Swzh020



Waterbody swzh020 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DRI Supply Bendline		Waterbody Name: UNT TO RICHWOOD RUN		Waterbody ID: SW26020	Date: 5-1-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s):		Milepost Entry: 30.2	Milepost Exit: 30.2	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>3</u> ft. Height: <u>1</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.		Depth of Water at Centerline: (Approx.) _____ ft.	
Sinuosity: (check one) ☒ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>1 1/2</u> ft. Left: <u>1 1/2</u> ft.	
Bank slope Right: <u>30</u> degrees Left: <u>30</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>70</u> % _____ % <u>20</u> % _____ % _____ %					
Width of Riparian Zone: <u>0</u> ft.		Vegetative Layers: (check all that apply) ☐ Trees: _____ ☐ Shrubs: _____ ☒ Herbs Avg. DBH of Dominants: _____ in. _____ in.			
Dominant Bank Vegetation: (list) <u>Dactylis glomerata, Festuca pratense, Taraxacum officinale</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles pools</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>NONE</u>					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Roadside run-off</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg020



Waterbody swzg020 facing upstream



Waterbody swzg020 facing downstream

Swzg020



Waterbody swzg020 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Wender</u>		Waterbody Name: XXXXXX <u>Arches Fork</u>		Waterbody ID: <u>SW2H021</u>	Date: <u>7-23-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>No parcel number listed</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM
Width: 25 ft.
Height: 3 ft.

OHWM Indicator: (check all that apply)
☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 35 ft.
 Width of Waterbody - Water Edge to Water Edge at Centerline: 8 ft.
 Depth of Water at Centerline: (Approx.) 8" ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) <5 fps

Bank height
Right: 5 ft.
Left: 5 ft.

Bank slope
Right: 80 degrees
Left: 90 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 70 % 5 % 15 % _____ %

Width of Riparian Zone: 15 ft.

Vegetative Layers: (check all that apply)
☒ Trees: 10" ☒ Shrubs: _____ ☒ Herbs
 Avg. DBH of Dominants: _____ in.

Dominant Bank Vegetation: (list)
Acer negundo, Platanus occidentalis, Microstegium umineae

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list)
Pools, riffles, overhanging veg

Aquatic Organisms Observed: (list)
small fish, small invertebrates

Invasive and/or T&E Species Observed: (list)
Microstegium umineae

Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent Road

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ4021

* **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh021



Waterbody swzh021 facing upstream



Waterbody swzh021 facing downstream

Swzh021



Waterbody swzh021 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>	Waterbody Name: <u>UNT TO Buffalo Run</u>	Waterbody ID: <u>SW24012</u>	Date: <u>7-23-15</u>
State: <u>WI</u>	County: <u>WETZEL</u>	Company: <u>ADQUEST</u>	Crew Member Initials: <u>SD, PP</u>
Tract Number(s): <u>33-001-1A002</u>	Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☐ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other: _____

OHWM
Width: 6 ft.
Height: 3" ft.

OHWM Indicator: (check all that apply)
☐ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining
☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft.
 Width of Waterbody - Water Edge to Water Edge at Centerline: 1 ft.
 Depth of Water at Centerline: (Approx.) 1/4" ft.

Sinuosity: (check one) ☒ Straight ☐ Meandering

Water velocity: (Approx.) <1 fps

Bank height
Right: 1 ft.
Left: 1 ft.

Bank slope
Right: 80 degrees
Left: 90 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 20 % 70 % _____ % 10 % _____ % _____ %

Width of Riparian Zone: 0 ft.

Vegetative Layers: (check all that apply)
☐ Trees: _____ in.
☒ Shrubs: _____ in.
☒ Herbs: _____ in.

Dominant Bank Vegetation: (list)
Impatiens capensis, Boehmeria cylindrica, Fagus grandifolia

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list)
R. Ayes

Aquatic Organisms Observed:

(list)
NONE

Invasive and/or T&E Species Observed:

(list)
Microstegium vimineum

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: roadside ditch

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZHO12

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh012



Waterbody swzh012 facing upstream



Waterbody swzh012 facing downstream

Swzh012



Waterbody swzh012 facing upline cross stream

Waterbody Data Sheet

Survey Description					
Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO BUFFALO RUN</u>		Waterbody ID: <u>SW2H002</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PA</u>	Photo ID(s):	
Tract Number(s): <u>NO NUMBER LISTED (PARCEL)</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					
Physical Attributes					
Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>8</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>12</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>5</u> ft.		Depth of Water at Centerline: (Approx.) <u>2"</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>< 2</u> fps		Bank height Right: <u>2</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>60</u> degrees Left: <u>60</u> degrees					
Qualitative Attributes					
Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>30</u> % <u>60</u> % <u>5</u> % <u>5</u> % _____ % _____ %					
Width of Riparian Zone: <u>225</u> ft. <u>on one side</u>		Vegetative Layers: (check all that apply) ☒ Trees: <u>8</u> in. ☒ Shrubs: _____ in. ☒ Herbs: _____			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Juglans nigra, Ulmus americana, Rosa multiflora, Microstegium</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>R. fls. pools</u>					
Aquatic Organisms Observed: (list) <u>small invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora</u>					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>adjacent Road</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.

~~SW2H002~~ 2 ←



swzh002



Waterbody swzh002 facing upstream



Waterbody swzh002 facing downstream

Swzh002



Waterbody swzh002 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Headcut</u>		Waterbody Name: <u>UNT RD</u>		Waterbody ID: <u>SW24003</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>ADWEST</u>	Crew Member Initials: <u>JD PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A004</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>2</u> ft. Height: <u>6"</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>8</u> ft.		Depth of Water at Centerline: (Approx.) <u>1/2"</u> ft.	
Sinuosity: (check one) ☒ Straight ☐ Meandering		Water velocity: (Approx.) <u>2</u> fps		Bank height Right: <u>2</u> ft. Left: <u>1</u> ft.	
Bank slope Right: <u>60</u> degrees Left: <u>30</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>70</u> % <u>10</u> % <u>10</u> % _____ % _____ %					
Width of Riparian Zone: <u>725</u> ft. <u>on one side</u>		Vegetative Layers: (check all that apply) ☒ Trees: <u>10</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Liriodendron tulipifera, Fagus grandifolia, Microstegium vimineum</u>					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles pools</u>					
Aquatic Organisms Observed: (list) <u>small invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>Microstegium vimineum</u>					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent forest road</u>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

SWZH003

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh003



Waterbody swzh003 facing upstream



Waterbody swzh003 facing downstream

Swzh003



Waterbody swzh003 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Line</u>		Waterbody Name: <u>UNT JD</u>		Waterbody ID: <u>SWZH004</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A004</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:

(check one)

☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:

Physical Attributes

Stream Classification:

(check one)

☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type:

(check one)

☒ Stream ☐ River ☒ Ditch ☐ Pond ☐ Lake ☐ Connecting swale^a ☐ Other:

OHWM

Width: 2 ft.

Height: 4" ft.

OHWM Indicator:

(check all that apply)

☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☒ Water staining
☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline:

4 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline:

1 ft.

Depth of Water at Centerline: (Approx.)

1/2" ft.

Sinuosity:

(check one)

☒ Straight
☐ Meandering

Water velocity:

(Approx.)

<1 fps

Bank height

Right: _____ ft.
Left: _____ ft.

Bank slope

Right: _____ degrees
Left: _____ degrees

Qualitative Attributes

Water Appearance:

(check one)

☐ No water ☐ Clear ☐ Turbid ☒ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate:

(check all that apply)

☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: _____ % 30 % 20 % 50 % _____ %

Width of Riparian Zone:

725 ft. one side

Vegetative Layers:

(check all that apply)

☒ Trees: 10 in. ☒ Shrubs: _____ in. ☒ Herbs

Avg. DBH of Dominants: (approx.)

Dominant Bank Vegetation:

(list)

Liriodendron tulipifera, Microstegium umineae, Boehmeria cylindrica

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list)

Pools

Aquatic Organisms Observed:

(list)

small invertebrates

Invasive and/or T&E Species Observed:

(list)

Microstegium umineae

Tributary is:

(check one)

☐ Natural ☒ Artificial, man-made ☒ Manipulated

Disturbances:

(check all that apply)

☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes

☒ Other:

Adjacent forest road

Stream Quality^b:

(check one)

☐ High ☒ Moderate ☐ Low

SWZH004

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh004



Waterbody swzh004 facing upstream



Waterbody swzh004 facing downstream

Swzh004



Waterbody swzh004 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT TO</u>		Waterbody ID: <u>SWZH005</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-001-A004</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>WWZH020</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>5</u> ft. Height: <u>6"</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>10</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>2</u> ft.		Depth of Water at Centerline: (Approx.) <u>1/2"</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>2</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>40</u> degrees Left: <u>40</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>60</u> % <u>10</u> % <u>20</u> % _____ % _____ %					
Width of Riparian Zone: _____ ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Carpinus caroliniana, Linodendron tulipifera, Boehmeria cylindrica</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles pools</u>					
Aquatic Organisms Observed: (list) <u>Small invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>M. cruzstegia uminea</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent forest road + pipeline</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

SWZH005

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh005



Waterbody swzh005 facing upstream



Waterbody swzh005 facing downstream

Swzh005



Waterbody swzh005 facing upline cross stream

Waterbody Data Sheet

Survey Description				
Project Name: Supply Hunker		Waterbody Name: UNT TO		Waterbody ID: SWZH006
Date: 7-22-15				
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, PP	Photo ID(s):
Tract Number(s): 33-001-A004		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:				
Physical Attributes				
Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial				
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other:				
OHWM Width: 3 ft. Height: 3" ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 4 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 6" ft.		Depth of Water at Centerline: (Approx.) NONE ft.
Sinuosity: (check one) ☒ Straight ☐ Meandering		Water velocity: (Approx.) <1 fps		Bank height Right: 1 ft. Left: 1 ft.
Bank slope Right: 30 degrees Left: 30 degrees				
Qualitative Attributes				
Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:				
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:				
% of Substrate: 20 % 60 % 5 % 15 % _____ %				
Width of Riparian Zone: >25 ft.		Vegetative Layers: (check all that apply) ☒ Trees: 10 in. ☒ Shrubs: _____ in. ☒ Herbs		
Avg. DBH of Dominants: (approx.) _____ in.				
Dominant Bank Vegetation: (list) Platanus occidentalis, Asimina triloba, Liriodendron benzoin, Athyrium filix-femina				
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Riffles				
Aquatic Organisms Observed: (list) NONE				
Invasive and/or T&E Species Observed: (list) NONE				
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated				
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: old forest road				
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low				

SWZH006

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh006



Waterbody swzh006 facing upstream



Waterbody swzh006 facing downstream

Swzh006



Waterbody swzh006 facing upline cross stream

Waterbody Data Sheet

Survey Description				
Project Name: <u>Supply Header</u>		Waterbody Name: <u>UNT JO</u>		Waterbody ID: <u>SWZ H007</u>
Date: <u>7-22-15</u>				
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DAWEST</u>	Crew Member Initials: <u>JD, PP</u>	Photo ID(s):
Tract Number(s): <u>33-001-A004</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other:				
Physical Attributes				
Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial				
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:				
OHWM Width: <u>2</u> ft. Height: <u>3</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>4</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.		Depth of Water at Centerline: (Approx.) _____ ft.
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>4</u> fps		Bank height Right: <u>6</u> " ft. Left: <u>6</u> " ft.
Bank slope Right: <u>20</u> degrees Left: <u>20</u> degrees				
Qualitative Attributes				
Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:				
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:				
% of Substrate: <u>10</u> % <u>60</u> % <u>10</u> % <u>20</u> % _____ % _____ %				
Width of Riparian Zone: <u>725</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs		
Avg. DBH of Dominants: (approx.) _____ in.				
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Fagus grandifolia, Athyrium filix-femina</u>				
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles</u>				
Aquatic Organisms Observed: (list) <u>NONE</u>				
Invasive and/or T&E Species Observed: (list) <u>Microstegium vimineum</u>				
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated				
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent Forest Road</u>				
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low				

SWZH007

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh007



Waterbody swzh007 facing upstream



Waterbody swzh007 facing downstream

Swzh007



Waterbody swzh007 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT to Carpenters Run		Waterbody ID: SW26028	Date: 5-13-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-A001		Milepost Entry: 26.3	Milepost Exit: 26.3	Associated Wetland ID(s): SW26028 WW26004 P W	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>8</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>12</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>3</u> ft.		Depth of Water at Centerline: (Approx.) <u>1</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>9</u> ft. Left: <u>10</u> ft.	
Bank slope Right: <u>80</u> degrees Left: <u>80</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>20</u> % <u>70</u> % <u>5</u> % <u>5</u> % _____ % _____ %					
Width of Riparian Zone: <u>>100</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in. _____ in.					
Dominant Bank Vegetation: (list) <u>Carpinus canadensis, Acer rubrum, Fagus grandifolia, Polystichum acrostichoides</u>					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>riffles, pools</u>					
Aquatic Organisms Observed: (list) <u>small invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>NONE</u>					
Stream Quality: ^b (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SW26028

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg028



Waterbody swzg028 facing upstream



Waterbody swzg028 facing downstream

Swzg028



Waterbody swzg028 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: Carpenters Run		Waterbody ID: SWZ6027	Date: 5-13-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-A001		Milepost Entry: 26.3	Milepost Exit: 26.3	Associated Wetland ID(s): WWZ6004FW	

Survey Type:
(check one)

- ☒ Centerline
 ☒ Re-Route
 ☐ Access Road
 ☐ Other:

Physical Attributes

Stream Classification:
(check one)

- ☐ Ephemeral
 ☐ Intermittent
 ☒ Perennial

Waterbody Type:
(check one)

- ☒ Stream
 ☐ River
 ☐ Ditch
 ☐ Pond
 ☐ Lake
 ☐ Connecting swale*
 ☐ Other:

OHWM

Width: 15 ft.

Height: ft.

OHWM Indicator:
(check all that apply)

- ☒ Clear line on bank
 ☒ Shelving
 ☒ Wrested vegetation
 ☐ Scouring
 ☐ Water staining
☒ Bent, matted, or missing vegetation
 ☒ Wrack line
 ☐ Litter and debris
 ☐ Abrupt plant community change
 ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline:

18 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline:

6 ft.

Depth of Water at Centerline:
(Approx.)

2" ft.

Sinuosity:
(check one)

- ☐ Straight
 ☒ Meandering

Water velocity:
(Approx.)

< 2 fps

Bank height

Right: 2 ft.

Left: 1 ft.

Bank slope

Right: 60 degrees

Left: 10 degrees

Qualitative Attributes

Water Appearance:
(check one)

- ☐ No water
 ☒ Clear
 ☐ Turbid
 ☐ Sheen on surface
 ☐ Surface scum
 ☐ Algal mats
 ☐ Other:

Substrate:
(check all that apply)

- ☒ Bedrock
 ☒ Gravel
 ☒ Sand
 ☒ Silt/clay
 ☐ Organic
 ☐ Other:

% of Substrate:

50 % 40 % 5 % 5 % % %

Width of Riparian Zone:

> 100 ft.

Vegetative Layers:
(check all that apply)

- ☒ Trees:
 ☒ Shrubs:
 ☒ Herbs
 Avg. DBH of Dominants: 10 in. in.

Dominant Bank Vegetation:

(list)
Carpinus virginiana, Acer rubrum, Fagus grandifolia, Rosa multiflora, Carex crinita

Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list)
riffles, pools, overhanging bank

Aquatic Organisms Observed:

(list)
small invertebrates

Invasive and/or T&E Species Observed:

(list)
Rosa multiflora

Tributary is:
(check one)

- ☒ Natural
 ☐ Artificial, man-made
 ☐ Manipulated

Disturbances:
(check all that apply)

- ☐ Livestock access
 ☐ Manure in waterbody
 ☐ Waste discharge pipes
 ☒ Other: NONE

Stream Quality:
(check one)

- ☐ High
 ☒ Moderate
 ☐ Low

Waterbody ID:

SWZ6027

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg027



Waterbody swzg027 facing upstream



Waterbody swzg027 facing downstream

Swzg027



Waterbody swzg027 facing upline cross stream

Waterbody Data Sheet

Description			
Project Name: Supply Header Project		Date: 06/02/2016	Waterbody Survey ID: swza002
State: WV	County/Parish: Wetzel	USGS Waterbody Name: Ash Camp Run	
Company: Dominion Transmission, Inc.	Crew Member Initials: KTC, LCE	Latitude:	Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)			
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)			
Water Appearance: ☐ No Water ☒ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)			
Feature Quality^a: ☒ High ☐ Moderate ☐ Low (check one)			
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)			
Flow Regime: ☐ Ephemeral ☐ Intermittent ☒ Perennial ☐ Connecting Swale (check one)			
Sinuosity within Survey Corridor: ☐ Straight ☒ Meandering (check one)			
Description Notes: High quality perennial stream adjacent to a lightly used dirt two-track access road.			
Measurements			
Depth of Water: <u>0.2</u> ft. ☐ N/A ☐ Unknown		Water Edge to Water Edge: <u>7</u> ft. ☐ N/A	
OHWM Width: <u>9</u> ft.			
OHWM Indicator: ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)			
☒ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☒ Soil characteristic change			
Dominant Substrate: ☐ Bedrock ☒ Boulder ☒ Cobble ☒ Gravel ☒ Sand ☐ Silt/ clay ☐ Organic (check all that apply)			
Observations			
Riparian Zone Present: ☒ Yes ☐ No (check one)			
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)			
Dominant Bank Vegetation (list): grass, forbs, ferns, moss; spicebush, hop-hornbeam, hornbeam, black walnut; basswood, hemlock, box elder, sycamore, elm			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): riffles, overhanging banks/roots, leaf packs, runs, bars, pools			
Aquatic Organisms Observed (list): fish, insects			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Adjacent two-track.			
Observation Notes: Riparian area with diverse flora and fauna.			

swaa002



Waterbody swza002 facing upstream



Waterbody swza002 facing downstream

swza002



Waterbody swza002 cross stream

Waterbody Data Sheet

Description			
Project Name: Supply Header Project		Date: 06/02/2016	Waterbody Survey ID: swza001
State: WV	County/Parish: Wetzel	USGS Waterbody Name: Unnamed tributary	
Company: Dominion Transmission, Inc.	Crew Member Initials: KTC, LCE	Latitude:	Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)			
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)			
Water Appearance: ☒ No Water ☐ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)			
Feature Quality^a: ☐ High ☒ Moderate ☐ Low (check one)			
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)			
Flow Regime: ☒ Ephemeral ☐ Intermittent ☐ Perennial ☐ Connecting Swale (check one)			
Sinuosity within Survey Corridor: ☒ Straight ☐ Meandering (check one)			
Description Notes: Ephemeral stream that flows into perennial stream swza002.			
Measurements			
Depth of Water: _____ ft. N/A ☒ Unknown ☐		Water Edge to Water Edge: _____ ft. N/A ☒	
OHWM Width: _____ ft.			
OHWM Indicator: ☐ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)			
☐ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☒ Soil characteristic change			
Dominant Substrate: ☐ Bedrock ☐ Boulder ☒ Cobble ☒ Gravel ☐ Sand ☒ Silt/ clay ☒ Organic (check all that apply)			
Observations			
Riparian Zone Present: ☐ Yes ☒ No (check one)			
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)			
Dominant Bank Vegetation (list): grass, forbs, ferns, moss; spicebush, beech; maple, oak, beech			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): n/a			
Aquatic Organisms Observed (list): n/a			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): n/a			
Observation Notes: steep slope; flow appears rare			

swza001



Waterbody swza001 facing upstream



Waterbody swza001 facing downstream

swza001



Waterbody swza001 cross stream

Waterbody Data Sheet

Description			
Project Name: Supply Header Project		Date: 06/02/2016	Waterbody Survey ID: swza003
State: WV	County/Parish: Wetzel	USGS Waterbody Name: unnamed tributary	
Company: Dominion Transmission, Inc.	Crew Member Initials: KTC, LCE	Latitude:	Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)			
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)			
Water Appearance: ☐ No Water ☒ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)			
Feature Quality^a: ☒ High ☐ Moderate ☐ Low (check one)			
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)			
Flow Regime: ☐ Ephemeral ☒ Intermittent ☐ Perennial ☐ Connecting Swale (check one)			
Sinuosity within Survey Corridor: ☒ Straight ☐ Meandering (check one)			
Description Notes: High quality intermittent stream confluences with swza002 .			
Measurements			
Depth of Water: <u>0.1</u> ft. ☐ N/A ☐ Unknown		Water Edge to Water Edge: <u>2</u> ft. ☐ N/A	
OHWM Width: <u>3</u> ft.			
OHWM Indicator: ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)			
☒ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☒ Soil characteristic change			
Dominant Substrate: ☒ Bedrock ☒ Boulder ☒ Cobble ☒ Gravel ☒ Sand ☐ Silt/ clay ☐ Organic (check all that apply)			
Observations			
Riparian Zone Present: ☐ Yes ☐ No (check one)			
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)			
Dominant Bank Vegetation (list): grass, forbs, ferns, moss; spicebush, maple; maple, hemlock, sycamore, elm			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): riffles, overhanging banks/roots, leaf packs, bars, step-pools			
Aquatic Organisms Observed (list): insects, salamander, crawfish			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes):			
Observation Notes: Very nice intermittent stream with cascading pools and seeping rocky banks.			

swza003



Waterbody swza003 facing upstream



Waterbody swza003 facing downstream

swza003



Waterbody swza003 cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Hender</u>		Waterbody Name: <u>UNT TO BUFFALO RUN</u>		Waterbody ID: <u>SWZ4001</u>	Date: <u>7-22-15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>DD, PP</u>	Photo ID(s):	
Tract Number(s): <u>33-009</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☒ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other: _____

OHWM Width: <u>3</u> ft. Height: _____ ft.	OHWM Indicator: (check all that apply)				
	☒ Clear line on bank	☐ Shelving	☒ Wrested vegetation	☐ Scouring	☒ Water staining
	☐ Bent, matted, or missing vegetation	☒ Wrack line	☐ Litter and debris	☐ Abrupt plant community change	☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: <u>6</u> ft.	Depth of Water at Centerline: (Approx.) <u>14</u> ft.
--	--	--

Sinuosity: (check one) ☒ Straight ☐ Meandering	Water velocity: (Approx.) <u><1</u> fps	Bank height Right: <u>3</u> ft. Left: <u>2</u> ft.	Bank slope Right: <u>20</u> degrees Left: <u>60</u> degrees
---	---	--	---

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☐ Turbid ☒ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 80 % 15 % _____ % 5 % _____ % _____ %

Width of Riparian Zone: <u>5</u> ft.	Vegetative Layers: (check all that apply)
	☐ Trees: _____ ☒ Shrubs: _____ ☒ Herbs
	Avg. DBH of Dominants: (approx.) _____ in. _____ in.

Dominant Bank Vegetation: (list) Rosa multiflora, microstegium, DA Daucus carota

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) riffles

Aquatic Organisms Observed: (list) NONE

Invasive and/or T&E Species Observed: (list) Rosa multiflora, Microstegium vimineum, Acalanthus altissimus

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: ROAD

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZH001

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzh001



Waterbody swzh001 facing upstream



Waterbody swzh001 facing downstream

Swzh001



Waterbody swzh001 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>Supply Hender</u>		Waterbody Name: <u>Fishing Creek</u>		Waterbody ID: <u>SW2H028</u>	Date: <u>7-29-18</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-009-0002 33-009-0001</u> <u>AC08</u>		Milepost Entry: <u>29.4</u>	Milepost Exit: <u>29.4</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>70</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☒ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>90</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>60</u> ft.		Depth of Water at Centerline: (Approx.) <u>3</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>75</u> fps		Bank height Right: <u>3</u> ft. Left: <u>4</u> ft.	
Bank slope Right: <u>30</u> degrees Left: <u>40</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>20</u> % <u>60</u> % <u>5</u> % <u>15</u> % _____ %					
Width of Riparian Zone: _____ ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>10</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Acer negundo, Polygonum cuspidatum, Elaeagnus umbellata</u> <u>Rosa multiflora</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles, pools, overhanging veg + banks, submerged</u>					
Aquatic Organisms Observed: (list) <u>Fish + invertebrates</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora, Polygonum cuspidatum, Elaeagnus umbellata</u> <u>Microstegium vimineum</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Adjacent lumber yard</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

SWZH028

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



SWZH028




Waterbody SWZH028
facing upstream



Waterbody SWZH028
facing downstream

SWZH028



Waterbody SWZH028 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: Supply Headbar Waterbody Name: UNT TO Fishing Creek Waterbody ID: SWZ H027 Date: 7-29-15

State: WV County: Wetzel Company: DDWEST Crew Member Initials: JD, DB Photo ID(s):

Tract Number(s): 33-009-C001 33-009 A008
33-009-C002 Milepost Entry: 29.4 Milepost Exit: 29.4 Associated Wetland ID(s): NDWE

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☒ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 4 ft. Height: ft. OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☒ Water staining ☒ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft. Width of Waterbody - Water Edge to Water Edge at Centerline: ft. Depth of Water at Centerline: (Approx.) 1' ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering Water velocity: (Approx.) <1 fps Bank height Right: 3 ft. Left: 3 ft. Bank slope Right: 40 degrees Left: 40 degrees

Qualitative Attributes

Water Appearance: (check one) ☒ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☒ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: % 70 % 10 % 20 % % %

Width of Riparian Zone: 10 ft. Vegetative Layers: (check all that apply) ☐ Trees: ☒ Shrubs: ☒ Herbs: ☒ Avg. DBH of Dominants: in. in.

Dominant Bank Vegetation: (list) Elaeagnus umbellata, Prunus serotina, Impatiens capensis

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Pools

Aquatic Organisms Observed: (list) NDWE

Invasive and/or T&E Species Observed: (list) Elaeagnus umbellata, Rosa multiflora, Microstegium vimineum

Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☒ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Adjacent to RR & timber yard

Stream Quality^b: (check one) ☐ High ☐ Moderate ☒ Low

* Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



SWZH027



Waterbody SWZH027
facing upstream



Waterbody SWZH027
facing downstream

SWZH027



Waterbody SWZH027 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: BTI Supply Header		Waterbody Name: UNT TO SOUTH FORK FISHING CREEK		Waterbody ID: SWZG014	Date: 5/1/15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-B019 33-009-A008		Milepost Entry: 28.9	Milepost Exit: 28.9	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☐ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☒ Other: CHANNELIZED					
OHWM Width: 3 ft. Height: 6" ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 5 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 2 ft.		Depth of Water at Centerline: (Approx.) 4" ft.	
Sinuosity: (check one) ☒ Straight ☐ Meandering		Water velocity: (Approx.) < 1 fps		Bank height Right: 1 ft. Left: 1 ft.	
Bank slope Right: 30 degrees Left: 30 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☒ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: _____ % 20 % _____ % 80 % _____ %					
Width of Riparian Zone: 0 ft.		Vegetative Layers: (check all that apply) ☐ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) Rosa multiflora, Elaeagnus umbellata, Dracopis glomerata					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Pools					
Aquatic Organisms Observed: (list) Small invertebrates					
Invasive and/or T&E Species Observed: (list) Rosa multiflora, Elaeagnus umbellata					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: channelized / next lumber yard					
Stream Quality ^b : (check one) ☐ High ☐ Moderate ☒ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg014



Waterbody swzg014 facing upstream



Waterbody swzg014 facing downstream

Swzg014



Waterbody swzg014 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNITO SOUTH FORK FISHING CREEK		Waterbody ID: SWZG016	Date: 5-1-15
State: WV	County: Wetzel	Company: DWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-B012 33-009-B018		Milepost Entry: 29.1	Milepost Exit: 29.1	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 4 ft. Height: 1 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 6 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: ft.		Depth of Water at Centerline: (Approx.) ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) 41 fps		Bank height Right: 3 ft. Left: 3 ft.	
Bank slope Right: 40 degrees Left: 70 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 10 % 80 % 5 % 5 % % %					
Width of Riparian Zone: 725 ft.		Vegetative Layers: (check all that apply) ☐ Trees: ☒ Shrubs: ☒ Herbs Avg. DBH of Dominants: in. in.			
Dominant Bank Vegetation: (list) <i>Elaeagnus umbellata</i> , <i>Viola</i> sp.					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) riffles, pools					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) <i>Elaeagnus umbellata</i>					

Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated	
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Nearby road	
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low	

Waterbody ID:

SWZ6016

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg016



Waterbody swzg016 facing upstream



Waterbody swzg016 facing downstream

Swzg016



Waterbody swzg016 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTN Supply Under		Waterbody Name: JNT TO SOUTH FORK FISHING CREEK		Waterbody ID: SWZ6015	Date: 5-1-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JC	Photo ID(s):	
Tract Number(s): 33-009-B012 33-009-B018		Milepost Entry: 29.1	Milepost Exit: 29.1	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☐ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☒ Other: CHANNELIZED					
OHWM Width: 3 ft. Height: 6 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 5 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 2 ft.		Depth of Water at Centerline: (Approx.) 3 ft.	
Sinuosity: (check one) ☒ Straight ☐ Meandering		Water velocity: (Approx.) < 1 fps		Bank height Right: 1 ft. Left: 1 ft.	
Bank slope Right: 30 degrees Left: 30 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☐ Turbid ☐ Sheen on surface ☒ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: _____ % 10 % _____ % 90 % _____ %					
Width of Riparian Zone: 0 ft.		Vegetative Layers: (check all that apply) ☐ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) Rosa multiflora, Eleagnus umbellata, Dactylis glomerata					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/rocks, leaf packs, large submerged wood, riffles, deep pools): (list) Pools					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) Rosa multiflora, Eleagnus umbellata					
Tributary is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: Next to road					
Stream Quality: (check one) ☐ High ☐ Moderate ☒ Low					

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg015



Waterbody swzg015 facing upstream



Waterbody swzg015 facing downstream

Swzg015



Waterbody swzg015 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT TO SOUTH FORK FISHWATER CREEK		Waterbody ID: SWZ6017	Date: 5-1-15
State: WV	County: Wetzel	Company: QUEST	Crew Member Initials: JD, JC	Photo ID(s):	
Tract Number(s): 33-009-B012 33-009-B018		Milepost Entry: 29.1	Milepost Exit: 29.1	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>4</u> ft. Height: <u>1</u> ft.		OHWM Indicator: (check all that apply) ☐ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>6</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.		Depth of Water at Centerline: (Approx.) <u>1/4</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>1</u> fps		Bank height Right: <u>2</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>60</u> degrees Left: <u>60</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>50</u> % <u>30</u> % <u> </u> % <u>10</u> % <u> </u> % <u> </u> %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>8</u> in. ☒ Shrubs: <u> </u> in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) <u>8</u> in.					
Dominant Bank Vegetation: (list) <u>Quercus alba, Prunus serotina, Rosa multiflora, Polystichum acrostichoides, Cornus florida</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>riffles</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>NEARBY ROAD</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

SWZG017

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg017



Waterbody swzg017 facing upstream



Waterbody swzg017 facing downstream

Swzg017



Waterbody swzg017 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: South Fork Fishing Creek		Waterbody ID: SWZ6018	Date: 5-1-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-0004 33-009-0012 33-009-0013 33-009-0018		Milepost Entry: 29.1	Milepost Exit: 29.4	Associated Wetland ID(s):	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☒ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 45 ft. Height: 4 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 60 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 35 ft.		Depth of Water at Centerline: (Approx.) 3 ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) 710 fps		Bank height Right: 8 ft. Left: 8 ft.	
				Bank slope Right: 30 degrees Left: 50 degrees	

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 20 % 50 % 5 % 25 % _____ % _____ %					
Width of Riparian Zone: 35 ft.		Vegetative Layers: (check all that apply) ☒ Trees: 8 in. ☒ Shrubs: _____ in. ☒ Herbs			
Dominant Bank Vegetation: (list) Acer negundo, Platanus occidentalis, Polygonum cuspidatum, Rosa multiflora, Dactylis glomerata					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Pool, riffles overhanging veg. submerged wood					
Aquatic Organisms Observed: (list) Small fish.					
Invasive and/or T&E Species Observed: (list) Rosa multiflora, Polygonum cuspidatum					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☒ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg018



Waterbody swzg018 facing upstream



Waterbody swzg018 facing downstream

Swzg018



Waterbody swzg018 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Vendor</u>		Waterbody Name: <u>Richwood Run</u>		Waterbody ID: <u>SWZ6019</u>	Date: <u>5-1-15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, JG</u>	Photo ID(s):	
Tract Number(s):		Milepost Entry: <u>30.2</u>	Milepost Exit: <u>30.2</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other: _____

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other: _____

OHWM Width: <u>15</u> ft. Height: _____ ft.	OHWM Indicator: (check all that apply)					
	☒ Clear line on bank	☒ Shelving	☒ Wrested vegetation	☐ Scouring	☐ Water staining	
	☒ Bent, matted, or missing vegetation	☒ Wrack line	☒ Litter and debris	☐ Abrupt plant community change	☐ Soil characteristic change	

Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>20</u> ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.	Depth of Water at Centerline: (Approx.) _____ ft.
---	---	--

Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) <u>72</u> fps	Bank height Right: <u>85</u> ft. Left: <u>6</u> ft.	Bank slope Right: <u>30</u> degrees Left: <u>45</u> degrees
---	--	---	---

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other: _____

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☐ Silt/clay ☐ Organic ☐ Other: _____

% of Substrate: 10 % 80 % _____ % 10 % _____ % _____ %

Width of Riparian Zone: <u>0</u> ft.	Vegetative Layers: (check all that apply)
	☐ Trees: _____ ☐ Shrubs: _____ ☒ Herbs
	Avg. DBH of Dominants: (approx.) _____ in. _____ in.

Dominant Bank Vegetation: (list)
Taraxacum officinale, Dactylis glomerata, Festuca pratensis, Brassica napus

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list)
Riffle, pools

Aquatic Organisms Observed: (list)
Small fish

Invasive and/or T&E Species Observed: (list)
Rosa multiflora

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☒ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other: _____

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ6019

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg019



Waterbody swzg019 facing upstream



Waterbody swzg019 facing downstream

Swzg019



Waterbody swzg019 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DRI Supply Bendline		Waterbody Name: UNT TO RICHWOOD RUN		Waterbody ID: SW26020	Date: 5-1-15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s):		Milepost Entry: 30.2	Milepost Exit: 30.2	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>3</u> ft. Height: <u>1</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>5</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.		Depth of Water at Centerline: (Approx.) _____ ft.	
Sinuosity: (check one) ☒ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>1 1/2</u> ft. Left: <u>1 1/2</u> ft.	
Bank slope Right: <u>30</u> degrees Left: <u>30</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☐ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>70</u> % _____ % <u>20</u> % _____ % _____ %					
Width of Riparian Zone: <u>0</u> ft.		Vegetative Layers: (check all that apply) ☐ Trees: _____ ☐ Shrubs: _____ ☒ Herbs Avg. DBH of Dominants: _____ in. _____ in.			
Dominant Bank Vegetation: (list) <u>Dactylis glomerata, Festuca pratense, Taraxacum officinale</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Riffles pools</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>NONE</u>					
Tributary is: (check one) ☐ Natural ☐ Artificial, man-made ☒ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Roadside run-off</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg020



Waterbody swzg020 facing upstream



Waterbody swzg020 facing downstream

Swzg020



Waterbody swzg020 facing upline cross stream

Waterbody Data Sheet

Description						
Project Name: Supply Header Project			Date: 06/03/2016		Waterbody Survey ID: swza006	
State: WV		County/Parish: Wetzel		USGS Waterbody Name: Unnamed tributary		
Company: Dominion Transmission, Inc.		Crew Member Initials: KTC, LCE		Latitude:		Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)						
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)						
Water Appearance: ☒ No Water ☐ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)						
Feature Quality^a: ☐ High ☒ Moderate ☐ Low (check one)						
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)						
Flow Regime: ☒ Ephemeral ☐ Intermittent ☐ Perennial ☐ Connecting Swale (check one)						
Sinuosity within Survey Corridor: ☒ Straight ☐ Meandering (check one)						
Description Notes: Ephemeral stream that flows out of survey corridor.						
Measurements						
Depth of Water: _____ ft. N/A ☒ Unknown ☐			Water Edge to Water Edge: _____ ft. N/A ☒		OHWM Width: <u>2</u> ft.	
OHWM Indicator: ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)						
☒ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☒ Soil characteristic change						
Dominant Substrate: ☐ Bedrock ☐ Boulder ☒ Cobble ☒ Gravel ☐ Sand ☒ Silt/ clay ☒ Organic (check all that apply)						
Observations						
Riparian Zone Present: ☐ Yes ☒ No (check one)						
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)						
Dominant Bank Vegetation (list): forbs, fern; maple, dogwood; maple, tuliptree						
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): n/a						
Aquatic Organisms Observed (list): n/a						
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): n/a						
Observation Notes: Upland drainage ephemeral stream						

swza006



Waterbody swza006 facing upstream



Waterbody swza006 facing downstream

swza006



Waterbody swza006 cross stream

Waterbody Data Sheet

Description			
Project Name: Supply Header Project		Date: 06/03/2016	Waterbody Survey ID: swza007
State: WV	County/Parish: Wetzel	USGS Waterbody Name: Unnamed tributary	
Company: Dominion Transmission, Inc.	Crew Member Initials: KTC, LCE	Latitude:	Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)			
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)			
Water Appearance: ☒ No Water ☐ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)			
Feature Quality^a: ☐ High ☒ Moderate ☐ Low (check one)			
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)			
Flow Regime: ☒ Ephemeral ☐ Intermittent ☐ Perennial ☐ Connecting Swale (check one)			
Sinuosity within Survey Corridor: ☒ Straight ☐ Meandering (check one)			
Description Notes: Ephemeral stream that drains upland forest.			
Measurements			
Depth of Water: _____ ft. N/A ☒ Unknown ☐		Water Edge to Water Edge: _____ ft. N/A ☒	
OHWM Width: _____ ft.			
OHWM Indicator: ☐ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)			
☒ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Dominant Substrate: ☐ Bedrock ☐ Boulder ☐ Cobble ☐ Gravel ☐ Sand ☒ Silt/ clay ☒ Organic (check all that apply)			
Observations			
Riparian Zone Present: ☐ Yes ☒ No (check one)			
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)			
Dominant Bank Vegetation (list): forbs; black gum, maple, rose; maple, beech			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): n/a			
Aquatic Organisms Observed (list): n/a			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): n/a			
Observation Notes: Upland drainage ephemeral stream; confluence with swza008.			

swza007



Waterbody swza007 facing upstream



Waterbody swza007 facing downstream

swza007



Waterbody swza007 cross stream

Waterbody Data Sheet

Description			
Project Name: Supply Header Project		Date: 06/03/2016	Waterbody Survey ID: swza008
State: WV	County/Parish: Wetzel	USGS Waterbody Name: Unnamed tributary	
Company: Dominion Transmission, Inc.	Crew Member Initials: KTC, LCE	Latitude:	Longitude:
Survey Type: ☒ Centerline ☐ Re-Route ☐ Access Road ☐ Facility ☐ Other (check one)			
Waterbody Type: ☐ River ☒ Stream ☐ Ditch ☐ Swale ☐ Canal ☐ Other (check one)			
Water Appearance: ☒ No Water ☐ Clear ☐ Turbid ☐ Sheen on Surface ☐ Surface Scum ☐ Algal Mats ☐ Other (check one)			
Feature Quality^a: ☐ High ☒ Moderate ☐ Low (check one)			
Feature Description: ☒ Natural ☐ Artificial, man-made ☐ Manipulated (check one)			
Flow Regime: ☒ Ephemeral ☐ Intermittent ☐ Perennial ☐ Connecting Swale (check one)			
Sinuosity within Survey Corridor: ☒ Straight ☐ Meandering (check one)			
Description Notes: Ephemeral stream that drains upland forest.			
Measurements			
Depth of Water: _____ ft. N/A ☒ Unknown ☐		Water Edge to Water Edge: _____ ft. N/A ☒	
OHWM Width: <u> 2 </u> ft.			
OHWM Indicator: ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☐ Scouring ☐ Water staining (check all that apply)			
☒ Bent, matted, or missing vegetation ☐ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Dominant Substrate: ☐ Bedrock ☐ Boulder ☒ Cobble ☒ Gravel ☒ Sand ☒ Silt/ clay ☐ Organic (check all that apply)			
Observations			
Riparian Zone Present: ☐ Yes ☒ No (check one)			
Vegetation Layers: ☒ Trees ☒ Saplings/Shrubs ☒ Herbs (check all that apply)			
Dominant Bank Vegetation (list): forbs, fern; beech, rose, maple, hornbeam; black gum, maple, oaks			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): n/a			
Aquatic Organisms Observed (list): n/a			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): n/a			
Observation Notes: Upland drainage ephemeral stream			

swza008



Waterbody swza008 facing upstream



Waterbody swza008 facing downstream

swza008



Waterbody swza008 cross stream

Waterbody Data Sheet

Survey Description					
Project Name: <u>DTI Supply Header</u>		Waterbody Name: <u>Upper Run</u>		Waterbody ID: <u>SOWZ6021</u>	Date: <u>5/12/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, JG</u>	Photo ID(s):	
Tract Number(s): <u>33-009-0025</u> <u>33-009-A017</u>		Milepost Entry: <u>29.9</u>	Milepost Exit: <u>29.9</u>	Associated Wetland ID(s):	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					
Physical Attributes					
Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other:					
OHWM Width: <u>20</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☒ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>30</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.		Depth of Water at Centerline: (Approx.) _____ ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>25</u> fps		Bank height Right: <u>4</u> ft. Left: <u>4</u> ft.	
				Bank slope Right: <u>30</u> degrees Left: <u>30</u> degrees	
Qualitative Attributes					
Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>40</u> % <u>40</u> % <u>10</u> % <u>10</u> % _____ % _____ %					
Width of Riparian Zone: <u>25</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: _____ in. ☒ Shrubs: _____ in. ☒ Herbs			
Aveg. DBH of Dominants: (approx.) _____ in. _____ in.					
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Acer rubrum, Rhus glabra, Rosa multiflora, Helianthus sp.</u> <u>barbatus, Verbesina occidentalis</u>					
Aquatic Habitats (ex. submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): <u>Pools, overhanging roots & veg, Riffles, leaf packs</u>					
Aquatic Organisms Observed: (list) <u>Several species of small fish, some showing breeding activity</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☒ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SWZG021

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg021



Waterbody swzg021 facing upstream



Waterbody swzg021 facing downstream

Swzg021



Waterbody swzg021 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Header</u>		Waterbody Name: <u>UNT TO UPPER RUN</u>		Waterbody ID: <u>SWZ6010</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DOWEST</u>	Crew Member Initials: <u>JD, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u> <u>33-009-A034</u>		Milepost Entry: <u>N</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: <u>100 Acre Mockingbird Site</u>					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>6</u> ft. Height: <u>9"</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>8</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>2</u> ft.		Depth of Water at Centerline: (Approx.) <u>3"</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u><1</u> fps		Bank height Right: <u>6</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>90</u> degrees Left: <u>60</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>60</u> % <u>15</u> % <u>15</u> % _____ % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>10</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Dominant Bank Vegetation: (list) <u>Acer negundo, Elaeagnus umbellata, Rosa multiflora, Equisetum hyemale</u>					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>Pools, riffles</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora, Elaeagnus umbellata</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>NONE</u>					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SWZ6010

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.



Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg010



Waterbody *swzg010*
facing upstream



Waterbody *swzg010*
downstream

swzg010



Waterbody swzg010 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Headwater		Waterbody Name: UNT TO UPPER RUN		Waterbody ID: SWZ6022	Date: 8/12/15
State: WV	County: Wetzel	Company: DEWEST	Crew Member Initials: JD, JG	Photo ID(s):	
Tract Number(s): 33-009-A017 33-009-A021		Milepost Entry: 31.3	Milepost Exit: 31.3	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 15 ft. Height: ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 18 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: ft.		Depth of Water at Centerline: (Approx.) ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) 21 fps		Bank height Right: 2 ft. Left: 2 ft.	
Bank slope Right: 60 degrees Left: 60 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 60% 30% 5% 5% % %					
Width of Riparian Zone: 7100 ft.		Vegetative Layers: (check all that apply) ☒ Trees: ☒ Shrubs: ☒ Herbs Avg. DBH of Dominants: in. in.			
Dominant Bank Vegetation: (list) <i>Carpinus caroliniana, Acer barbatum, Athyrum filix-Femina</i>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <i>Pools, Riffles</i>					
Aquatic Organisms Observed: (list) <i>small fish, amphibians</i>					
Invasive and/or T&E Species Observed: (list) <i>NONE</i>					

Tributary Is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated			
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <i>NONE</i>			
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low			

Waterbody ID:

SWZ6022

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg022



Waterbody swzg022 facing upstream



Waterbody swzg022 facing downstream

Swzg022



Waterbody swzg022 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: D7 Supply Hender		Waterbody Name: Lower Run		Waterbody ID: SW26023	Date: 5/12/15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, JB	Photo ID(s):	
Tract Number(s): 33-009-C028		Milepost Entry: 32.3	Milepost Exit: 32.3	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 87 ft.
Height: 9 ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 14 ft.
Width of Waterbody - Water Edge to Water Edge at Centerline: 5 ft.
Depth of Water at Centerline: (Approx.) 1 ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering

Water velocity: (Approx.) 22 fps

Bank height Right: 1 ft. Left: 1 ft.

Bank slope Right: 15 degrees Left: 15 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 20 % 70 % 5 % 5 %

Width of Riparian Zone: 20 ft.

Vegetative Layers: (check all that apply) ☒ Trees: ☒ Shrubs: ☒ Herbs

Avg. DBH of Dominants: in.

Dominant Bank Vegetation: (list) *Platanus occidentalis, LARPINUS, CAROLINIANA, FRAXINUS PENNSYLANICANA, LINDBA BERZONI, URBASIMA OCCIDENTALIS*

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) *riffle, pools, over hanging veg.*

Aquatic Organisms Observed: (list) *Small fish + frogs*

Invasive and/or T&E Species Observed: (list) *NONE*

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: *Adjacent*

Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ6023

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg023



Waterbody swzg023 facing upstream



Waterbody swzg023 facing downstream

Swzg023



Waterbody swzg023 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: Upper RUN Lower		Waterbody ID: SWZG008	Date: 4/22/15
State: WV	County: Wetzel	Company: DD WEST	Crew Member Initials: JD, DB	Photo ID(s):	
Tract Number(s): 33-011		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100 Acre Mockingbird Side

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 14 ft. Height: _____ ft.	OHWM Indicator: (check all that apply)				
	☒ Clear line on bank	☒ Shelving	☒ Wrested vegetation	☒ Scouring	☐ Water staining
	☒ Bent, matted, or missing vegetation	☒ Wrack line	☐ Litter and debris	☐ Abrupt plant community change	☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 20 ft.	Width of Waterbody - Water Edge to Water Edge at Centerline: 12 ft.	Depth of Water at Centerline: (Approx.) 4" ft.
--	--	---

Sinuosity: (check one) ☐ Straight ☒ Meandering	Water velocity: (Approx.) 75 fps	Bank height Right: 3 ft. Left: 2 ft.	Bank slope Right: 90 degrees Left: 40 degrees
---	-------------------------------------	--	---

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 10 % 70 % 10 % 10 % _____ % _____ %

Width of Riparian Zone: 750 ft.	Vegetative Layers: (check all that apply)
	☒ Trees: 15 in. ☒ Shrubs: _____ in. ☒ Herbs
	Avg. DBH of Dominants: (approx.)

Dominant Bank Vegetation: (list) *Platanus occidentalis, Rosa multiflora, Elaeagnus umbellata, Microstegium Uiminia, Dactylis glomerata*

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) *Pools, R. fls, overhanging bank + veg.*

Aquatic Organisms Observed: (list) *small fish*

Invasive and/or T&E Species Observed: (list) *Rosa multiflora, Elaeagnus umbellata*

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZG008

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg008



Waterbody *swzg008*
facing upstream



Waterbody *swzg008*
downstream

swzg008



Waterbody swzg008 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Header</u>		Waterbody Name: <u>LOWER UNT TO UPPER RUN</u>		Waterbody ID: <u>SWZG009</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>ID, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u> <u>33-009-A034</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>WWZG002</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: <u>100 Acre Mockingbird Site</u>					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: <u>15</u> ft. Height: <u>6</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>20</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: _____ ft.		Depth of Water at Centerline: (Approx.) <u>6</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>72</u> fps		Bank height Right: <u>1</u> ft. Left: <u>1</u> ft.	
Bank slope Right: <u>15</u> degrees Left: <u>15</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>20</u> % <u>20</u> % <u>5</u> % <u>5</u> % _____ % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>12</u> in. ☒ Shrubs: _____ in. ☒ Herbs			
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Acer negundo, Rosa multiflora, Lamium purpureum, Pteris aquilina</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>in the pool</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>Rosa multiflora</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>NONE</u>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SWZ6009

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.



Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg009



Waterbody *swzg009*
facing upstream



Waterbody *swzg009*
downstream

swzg009



Waterbody swzg009 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DT/Supply Henders		Waterbody Name: SOUTH FORK FISHING CREEK		Waterbody ID: SWZG003	Date: 4/22/15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, DB	Photo ID(s):	
Tract Number(s): 33-011		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	

Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100 Acre Modeling and Site

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial

Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:

OHWM Width: 110 ft. Height: 1 ft.

OHWM Indicator: (check all that apply) ☒ Clear line on bank ☒ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline: 130 ft. Width of Waterbody - Water Edge to Water Edge at Centerline: 100 ft. Depth of Water at Centerline: (Approx.) 6 ft.

Sinuosity: (check one) ☐ Straight ☒ Meandering Water velocity: (Approx.) 7.5 fps Bank height Right: 8 ft. Left: 6 ft. Bank slope Right: 80 degrees Left: 80 degrees

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:

Substrate: (check all that apply) ☐ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:

% of Substrate: 20 % 40 % 40 %

Width of Riparian Zone: 10 ft. Vegetative Layers: (check all that apply) ☒ Trees: 10 in. ☒ Shrubs: ☒ Herbs

Avg. DBH of Dominants: (approx.)

Dominant Bank Vegetation: (list) Acer negundo, Populus deltoides, Platanus occidentalis, Rumex crispus

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Pool, overhanging veg + bank

Aquatic Organisms Observed: (list) small fish, tadpoles

Invasive and/or T&E Species Observed: (list) NONE

Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated

Disturbances: (check all that apply) ☒ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:

Stream Quality^b: (check one) ☐ High ☒ Moderate ☐ Low

Waterbody ID:

SWZ6003

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg003



Waterbody *swzg003*
facing upstream



Waterbody *swzg003*
downstream

swzg003



Waterbody swzg003 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT TO SOUTH FORK FISHING CREEK		Waterbody ID: SWZG004	Date: 4/22/15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, DB	Photo ID(s):	
Tract Number(s): 33-011		Wilepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100 Acre Mockingbird site					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 6 ft. Height: 0.5 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 10 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 2 ft.		Depth of Water at Centerline: (Approx.) _____ ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) 72 fps		Bank height Right: 4 ft. Left: 5 ft.	
Bank slope Right: 80 degrees Left: 80 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 30 % 60 % 5 % 5 % _____ %					
Width of Riparian Zone: > 20 ft.		Vegetative Layers: (check all that apply) ☒ Trees: ☒ Shrubs: ☒ Herbs Avg. DBH of Dominants: _____ in.			
Dominant Bank Vegetation: (list) Ulmus americana, Acer negundo, Elaeagnus umbellata, Polystichum acrostichoides, Lonicera japonica					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Riffle, pools					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) Elaeagnus umbellata					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: pipeline easement					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SW26004

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg004



Waterbody *swzg004*
facing upstream



Waterbody *swzg004*
downstream

swzg004



Waterbody swzg004 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: DTI Supply Header		Waterbody Name: UNT TO SOUTH FORK FISHING CREEK		Waterbody ID: SWZG001	Date: 4/22/15
State: WV	County: Wetzel	Company: DOWEST	Crew Member Initials: JD, D.B.	Photo ID(s):	
Tract Number(s): 33-011 33-009-A036		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100 Acre Mockingbird Site					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 4 ft. Height: 6" ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☐ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 2 ft.		Depth of Water at Centerline: (Approx.) 2" ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) 12 fps		Bank height Right: 3 ft. Left: 3 ft.	
Bank slope Right: 90 degrees Left: 90 degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 70 % 20 % 5 % 5 % % %					
Width of Riparian Zone: 750 ft.		Vegetative Layers: (check all that apply) ☒ Trees: 8 in. ☒ Shrubs: ☒ Herbs			
Avg. DBH of Dominants: (approx.)					
Dominant Bank Vegetation: (list) Acer negundo, Elaeagnus umbellata, Rubus leucodermis, Geranium maculatum, Rosa multiflora					
Aquatic Habitats (ex. submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Riffle pools					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) Rosa multiflora					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: NONE					
Stream Quality: (check one) ☒ High ☐ Moderate ☐ Low					

Waterbody ID:

SWZG001

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg001



Waterbody *swzg001*
facing upstream



Waterbody *swzg001*
downstream

swzg001



Waterbody swzg001 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTL Supply Hender</u>		Waterbody Name: <u>UNT TO SOUTH FORK FISHING CREEK</u>		Waterbody ID: <u>SW26002</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, DB.</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u> <u>33-009-A036</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: <u>100 Acre Mockingbird Site</u>					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ^a ☐ Other:					
OHWM Width: <u>4</u> ft. Height: <u>1</u> ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>8</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.		Depth of Water at Centerline: (Approx.) <u>1</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>< 1</u> fps		Bank height Right: <u>2</u> ft. Left: <u>2</u> ft.	
Bank slope Right: <u>50</u> degrees Left: <u>70</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>60</u> % <u>35</u> % <u>2</u> % <u>3</u> % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: <u>10</u> in. ☒ Shrubs: <u>10</u> in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) <u>10</u> in.					
Dominant Bank Vegetation: (list) <u>Platanus occidentalis, Cornus florida, Elaeagnus umbellata, Polystichum acrostichoides</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>rifle, pools</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>Elaeagnus umbellata</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☒ Other: <u>Encasement/ Site Development</u>					
Stream Quality: (check one) ☐ High ☒ Moderate ☐ Low					

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg002



Waterbody *swzg002*
facing upstream



Waterbody *swzg002*
downstream

swzg002



Waterbody swzg002 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Header</u>		Waterbody Name: <u>UNT TO UPPER RUN</u>		Waterbody ID: <u>SWZG007</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>WETZEL</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u> <u>33-009-A034, 33-009-A035</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:

(check one)

☐ Centerline

☐ Re-Route

☐ Access Road

☒ Other:

100 Acre Mockingbird Site

Physical Attributes

Stream Classification:

(check one)

☐ Ephemeral

☐ Intermittent

☒ Perennial

Waterbody Type:

(check one)

☒ Stream

☐ River

☐ Ditch

☐ Pond

☐ Lake

☐ Connecting swale*

☐ Other:

OHWM

Width: 6 ft.

Height: 0.5 ft.

OHWM Indicator:

(check all that apply)

☒ Clear line on bank

☐ Shelving

☐ Wrested vegetation

☒ Scouring

☐ Water staining

☒ Bent, matted, or missing vegetation

☒ Wrack line

☐ Litter and debris

☐ Abrupt plant community change

☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline:

10 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline:

4 ft.

Depth of Water at Centerline:

(Approx.)

2 ft.

Sinuosity:

(check one)

☐ Straight

☒ Meandering

Water velocity:

(Approx.)

< 2 fps

Bank height

Right: 2 ft.

Left: 2 ft.

Bank slope

Right: 60 degrees

Left: 70 degrees

Qualitative Attributes

Water Appearance:

(check one)

☐ No water

☐ Clear

☒ Turbid

☐ Sheen on surface

☐ Surface scum

☐ Algal mats

☐ Other:

Substrate:

(check all that apply)

☒ Bedrock

☒ Gravel

☒ Sand

☒ Silt/clay

☐ Organic

☐ Other:

% of Substrate:

35 %

50 %

10 %

5 %

 %

 %

Width of Riparian Zone:

750 ft.

Vegetative Layers:

(check all that apply)

☒ Trees:

☒ Shrubs:

☒ Herbs

Avg. DBH of Dominants:

(approx.)

10 in.

 in.

Dominant Bank Vegetation:

(list) Platanus occidentalis, Acer negundo, Populus deltoides, Trillium grandiflora

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list)

rifle, pools

Aquatic Organisms Observed:

(list)

NONE

Invasive and/or T&E Species Observed:

(list)

Rosa multiflora

Tributary is:

(check one)

☒ Natural

☐ Artificial, man-made

☐ Manipulated

Disturbances:

(check all that apply)

☐ Livestock access

☐ Manure in waterbody

☒ Waste discharge pipes

☐ Other:

Stream Quality^b:

(check one)

☐ High

☒ Moderate

☐ Low

Waterbody ID:

SWZ6007

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg007



Waterbody *swzg007*
facing upstream



Waterbody *swzg007*
downstream

swzg007



Waterbody swzg007 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Henske</u>		Waterbody Name: <u>UNT TO LOWER RUN</u>		Waterbody ID: <u>SWZG007</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DD WEST</u>	Crew Member Initials: <u>JD, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u> <u>33-009-A034</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: <u>100 Acre Mockingbird Site</u>					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: <u>3</u> ft. Height: _____ ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: <u>8</u> ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: <u>1</u> ft.		Depth of Water at Centerline: (Approx.) <u>1"</u> ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) <u>< 1</u> fps		Bank height Right: <u>6"</u> ft. Left: <u>6"</u> ft.	
Bank slope Right: <u>15</u> degrees Left: <u>15</u> degrees					

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: <u>10</u> % <u>70</u> % <u>10</u> % <u>10</u> % _____ %					
Width of Riparian Zone: <u>750</u> ft.		Vegetative Layers: (check all that apply) ☒ Trees: ☒ Shrubs: ☒ Herbs			
Avg. DBH of Dominants: (approx.) _____ in.					
Dominant Bank Vegetation: (list) <u>Box elder, Viola rotundifolia, Cardamine bulbosa, Cercis canadensis, Acer negundo</u>					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) <u>little pools</u>					
Aquatic Organisms Observed: (list) <u>NONE</u>					
Invasive and/or T&E Species Observed: (list) <u>ROSE Rosa multiflora</u>					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: <u>NONE</u>					
Stream Quality: (check one) ☒ High ☐ Moderate ☐ Low					

SW26007

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



Swzg007 intermittent



Waterbody *swzg007 intermittent*
facing upstream



Waterbody *swzg007 intermittent*
downstream

Swzg007 intermittent



Waterbody swzg007 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: D&I Supply Hauler		Waterbody Name: UNT TO UPPER RUN		Waterbody ID: SWZG006	Date: 4/22/15
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, DB	Photo ID(s):	
Tract Number(s): 33-009-A034 33-011 33-009-A035		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): WWZG001ew	
Survey Type: (check one) ☐ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100Aero Mockingbird Site					

Physical Attributes

Stream Classification: (check one) ☐ Ephemeral ☐ Intermittent ☒ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale * ☐ Other:					
OHWM Width: 10 ft. Height: ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☒ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 14 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: 3 ft.		Depth of Water at Centerline: (Approx.) 4" ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) > 2 fps		Bank height Right: 1 ft. Left: 2 ft.	
				Bank slope Right: 70 degrees Left: 80 degrees	

Qualitative Attributes

Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 10 % 75 % 10 % 5 % %					
Width of Riparian Zone: 750 ft.		Vegetative Layers: (check all that apply) ☒ Trees: 10 in. ☒ Shrubs: in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) 10 in.					
Dominant Bank Vegetation: (list) PLATANUS OCCIDENTALIS, PODOPHYLLUM PELTATUM, ACER NEGUNDO, PHLOX CAROLINIANA					
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) R. fly pools					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) ROSA MULTIFLORA					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☒ Waste discharge pipes ☐ Other:					
Stream Quality ^b : (check one) ☐ High ☒ Moderate ☐ Low					

Waterbody ID:

SWZ6006

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg006



Waterbody *swzg006*
facing upstream



Waterbody *swzg006*
downstream

swzg006



Waterbody swzg006 facing upline cross stream

Waterbody Data Sheet

Survey Description					
Project Name: DTI Supply Hender		Waterbody Name: UNT		Waterbody ID: SWZG006	Date: 4/22/15
State: WV	County: Wetzel	Company: DQUEST	Crew Member Initials: JD, DB	Photo ID(s):	
Tract Number(s): 33-009-A034		Milepost Entry: NA	Milepost Exit: NA	Associated Wetland ID(s): NONE	
Survey Type: (check one) ☒ Centerline ☐ Re-Route ☐ Access Road ☒ Other: 100 acre Mockingbird Site					
Physical Attributes					
Stream Classification: (check one) ☐ Ephemeral ☒ Intermittent ☐ Perennial					
Waterbody Type: (check one) ☒ Stream ☐ River ☐ Ditch ☐ Pond ☐ Lake ☐ Connecting swale ☐ Other:					
OHWM Width: 4 ft. Height: 1 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☒ Scouring ☐ Water staining ☒ Bent, matted, or missing vegetation ☒ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change			
Width of Waterbody - Top of Bank to Top of Bank at Centerline: 8 ft.		Width of Waterbody - Water Edge to Water Edge at Centerline: ft.		Depth of Water at Centerline: (Approx.) ft.	
Sinuosity: (check one) ☐ Straight ☒ Meandering		Water velocity: (Approx.) < 1 fps		Bank height Right: 1 ft. Left: 1 ft.	
Bank slope Right: 35 degrees Left: 35 degrees					
Qualitative Attributes					
Water Appearance: (check one) ☐ No water ☒ Clear ☐ Turbid ☐ Sheen on surface ☐ Surface scum ☐ Algal mats ☐ Other:					
Substrate: (check all that apply) ☒ Bedrock ☒ Gravel ☒ Sand ☒ Silt/clay ☐ Organic ☐ Other:					
% of Substrate: 60% 30% 5% 5% % %					
Width of Riparian Zone: 7 ft.		Vegetative Layers: (check all that apply) ☒ Trees: 8 in. ☒ Shrubs: in. ☒ Herbs			
Avg. DBH of Dominants: (approx.) 8 in.					
Dominant Bank Vegetation: (list) Acer rubrum, Polystichum acrostoides, Trillium grandiflora, Rosa multiflora					
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): (list) Riffle, pool					
Aquatic Organisms Observed: (list) NONE					
Invasive and/or T&E Species Observed: (list) Rosa multiflora					
Tributary is: (check one) ☒ Natural ☐ Artificial, man-made ☐ Manipulated					
Disturbances: (check all that apply) ☐ Livestock access ☐ Manure in waterbody ☐ Waste discharge pipes ☐ Other: NONE					
Stream Quality: (check one) ☒ High ☐ Moderate ☐ Low					

Waterbody ID: *INTERMITTENT*
SWZ6006

^a Connecting swales are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



Swzg006 intermittent



Waterbody *swzg006 intermittent*
facing upstream



Waterbody *swzg006 intermittent*
downstream

Swzg006 intermittent



Waterbody swzg006 facing upline cross stream

Waterbody Data Sheet

Survey Description

Project Name: <u>DTI Supply Header</u>		Waterbody Name: <u>UNT TO UPPER RUN</u>		Waterbody ID: <u>SWZ6005</u>	Date: <u>4/22/15</u>
State: <u>WV</u>	County: <u>Wetzel</u>	Company: <u>DDWEST</u>	Crew Member Initials: <u>JD, DB</u>	Photo ID(s):	
Tract Number(s): <u>33-011</u>		Milepost Entry: <u>NA</u>	Milepost Exit: <u>NA</u>	Associated Wetland ID(s): <u>NONE</u>	

Survey Type:
(check one)

☐ Centerline

☐ Re-Route

☐ Access Road

☒ Other:

100 Acre Mockingbird Site

Physical Attributes

Stream Classification:
(check one)

☐ Ephemeral

☐ Intermittent

☒ Perennial

Waterbody Type:
(check one)

☒ Stream

☐ River

☐ Ditch

☐ Pond

☐ Lake

☐ Connecting swale^a

☐ Other:

OHWM

Width: 6 ft.

Height: 6" ft.

OHWM Indicator:
(check all that apply)

☒ Clear line on bank

☐ Shelving

☒ Wrested vegetation

☐ Scouring

☐ Water staining

☒ Bent, matted, or missing vegetation

☒ Wrack line

☐ Litter and debris

☐ Abrupt plant community change

☐ Soil characteristic change

Width of Waterbody - Top of Bank to Top of Bank at Centerline:

10 ft.

Width of Waterbody - Water Edge to Water Edge at Centerline:

3 ft.

Depth of Water at Centerline:
(Approx.)

1" ft.

Sinuosity:
(check one)

☐ Straight

☒ Meandering

Water velocity:
(Approx.)

<1 fps

Bank height

Right: _____ ft.

Left: _____ ft.

Bank slope

Right: _____ degrees

Left: _____ degrees

Qualitative Attributes

Water Appearance:
(check one)

☐ No water

☐ Clear

☒ Turbid

☐ Sheen on surface

☐ Surface scum

☐ Algal mats

☐ Other:

Substrate:
(check all that apply)

☒ Bedrock

☒ Gravel

☒ Sand

☒ Silt/clay

☐ Organic

☐ Other:

% of Substrate:

20 %

70 %

5 %

5 %

_____ %

_____ %

Width of Riparian Zone:

>250 ft.

Vegetative Layers:
(check all that apply)

☒ Trees:

10 in.

☒ Shrubs:

_____ in.

☒ Herbs

Avg. DBH of Dominants:
(approx.)

Dominant Bank Vegetation:

(list) Platanus occidentalis, Acer negundo, Phlox caroliniana, Podophyllum peltatum

Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools):

(list) R. Hle, pools

Aquatic Organisms Observed:

(list) NONE

Invasive and/or T&E Species Observed:

(list) NONE

Tributary is:
(check one)

☒ Natural

☐ Artificial, man-made

☐ Manipulated

Disturbances:
(check all that apply)

☐ Livestock access

☐ Manure in waterbody

☐ Waste discharge pipes

☐ Other:

NONE

Stream Quality^b:
(check one)

☐ High

☒ Moderate

☐ Low

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



swzg005



Waterbody *swzg005*
facing upstream



Waterbody *swzg005*
downstream

swzg005



Waterbody swzg005 facing upline cross stream

Open Waterbody Data Sheet

Survey Description				
Project Name: BTH Supply Hender		Waterbody Name: OLD POND BELOW LANDFILL		Waterbody ID: OWZ6001
Date: 4/22/15				
State: WV	County: Wetzel	Company: DDWEST	Crew Member Initials: JD, DB	Photos:
Tract Number(s): 33-009-A034		Nearest Milepost: NA		Associated Wetland ID(s): NONE
Survey Type: (check one) ☒ Centerline ☒ Re-Route ☐ Access Road ☐ Other:				
Physical Attributes				
Waterbody Type: (check one) ☐ Stock Pond ☐ Natural Pond ☐ Lake ☐ Reservoir ☒ Impoundment ☐ Oxbow ☐ Other:				
Hydrologic Regime: ☒ Permanently Flooded ☐ Semipermanently Flooded ☐ Seasonally Flooded ☐ Temporarily Flooded				
OHWM Height: 4 ft.		OHWM Indicator: (check all that apply) ☒ Clear line on bank ☐ Shelving ☐ Wrested vegetation ☒ Scouring ☐ Water staining ☐ Bent, matted, or missing vegetation ☐ Wrack line ☐ Litter and debris ☐ Abrupt plant community change ☐ Soil characteristic change		
Depth of Water: N/A ft.		Bank height (average): 76 ft.		Bank slope (average): 30 degrees
Qualitative Attributes				
Water Appearance: (check one) ☐ No water ☐ Clear ☒ Turbid ☐ Sheen on surface ☒ Surface scum ☐ Algal mats ☐ Other:				
Substrate: (check all that apply) ☐ Bedrock ☐ Boulder ☐ Cobble ☒ Gravel ☒ Sand ☒ Silt/clay ☒ Organic ☐ Other:				
% of Substrate: _____% _____% _____% 30% 30% 30% 10% _____%				
Width of Riparian Zone: 725 ft.		Vegetative Layers: (check all that apply) ☒ Trees: ☒ Saplings/Shrubs: ☒ Herbs Avg. DBH of Dominants: 10 in. 2 in. _____ in.		
Dominant Bank Vegetation (list): Salix nigra, Platanus occidentalis				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.): POOL				
Aquatic Organisms Observed (list): small frogs, tadpoles				
T&E Species Observed (list): Rosa multiflora, Elaeagnus umbellata				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): at base of old land w/ waste water issuing into pond				
Waterbody is: (check one) ☐ Natural ☒ Artificial, man-made ☐ Manipulated				
Waterbody Quality *: (check one) ☐ High ☐ Moderate ☒ Low				

Waterbody ID:

DWZG001

^a **Connecting swales** are water features that do not meet the definition of a waterbody (not an ephemeral waterbody) in that there is not a defined bed, bank, and ordinary high water mark, however, it is a water conveyance feature that is characterized by flow volume, frequency, and duration to make it more than just an erosional feature and connects two potential waters of the U.S. and thereby may be subject to Section 404 permitting.

^b **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes

DWZG006

Waterbody Sketch

Include north arrow, centerline, distance from centerline, photo locations, survey boundary, and unique IDs of associated features.



owzg001



Waterbody *owzg001*
facing upstream



Waterbody *owzg001*
downstream

owzg001



Waterbody owzg001 facing upline cross stream