

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Warwick Run	
Waterbody ID: shia407		Date: 5/3/2016	
State: Virginia	County: Highland	Company: NRG - ERM	Crew Member Initials: GB, SA
Photos: 5 photos			
Tract Number(s): 06-001-B001 - GWNF		Nearest Milepost: 84.85	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 20.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
OHWM Height: 1.5 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: 28.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 10.0 ft.	Width of Waterbody - Water Edge to Water Edge: 16.0 ft.	Depth of Water: <i>(Approx.)</i> 0.75 ft.
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.5 fps	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Bank height Right: 4.5 ft. Left: 5.0 ft.		Bank slope Right: 75 degrees Left: 70 degrees	
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks show signs of instability in places evidenced by loose rocks and soils; this would be considered normal for a moderately steep gradient stream.			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input checked="" type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      10%      50%      25%      10%      _____%      5%      _____%			
Width of Riparian Zone: 175 ft.		Vegetative Layers: <i>(check all that apply)</i>	
N/A <input type="checkbox"/>		<input checked="" type="checkbox"/> Trees: 14.0 in. <input checked="" type="checkbox"/> Saplings/Shrubs: 1.0 in. <input checked="" type="checkbox"/> Herbs: -	
Dominant Bank Vegetation (list): Hemlock, white pine, sugar maple, green ash, basswood, sweet birch, yellow poplar, hydrangea, striped maple, Dutchman's pipe, Christmas fern, violet, wood aster, blackberry, wood fern			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Riffles, scattered pools, woody debris, wrack piles			
Aquatic Organisms Observed (list): Water striders, invertebrates, minnows, crayfish			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

Waterbody ID:

shia407

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Continues out of corridor in both directions; channel is braided – OHWM added for braids; bank to bank outermost to outermost. Stream is of a moderately steep gradient with bed dominated by cobble. Mature second growth mixed hardwoods with hemlock and white pine; canopy sparse in places due to hemlock and white pine mortality.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)

**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low



↑N

SB

Mature 2nd growth  
mixed HWs with  
hemlock &  
white pine  
throughout


Point

SHIA007  
UNT to Warwick Run  
Peachvine Stream  
BRAIDED  
CHANNEL

150'

150'

SB





Waterbody SHIA407 facing north upstream



Waterbody SHIA407 facing south downstream





Waterbody SHIA407 facing west across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Warwick Run	
Waterbody ID: shia410		Date: 5/7/2016	
State: Virginia	County: Highland	Company: NRG-ERM	Crew Member Initials: GB, SA
Photos: 5			
Tract Number(s): 06-001-B001-GWNF		Nearest Milepost: 85.1	Associated Wetland ID(s): No associated wetlands
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 12 ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
OHWM Height: 1 ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: 18 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 8 ft.	Width of Waterbody - Water Edge to Water Edge: 9 ft.	Depth of Water: <i>(Approx.)</i> 0.5 ft.
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 2 fps	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Bank height Right: 4 ft. Left: 5 ft.		Bank slope Right: 80 degrees Left: 70 degrees	
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Evidence of bank instability in the form of loose rocks and soil; to be expected on high gradient streams			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      60%      25%      10%      _____%      5%      _%			
Width of Riparian Zone: 100 ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs	
N/A <input type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> 14 in.      1.5 in.      -	
Dominant Bank Vegetation (list): Hemlock, white pine, sugar maple, yellow poplar, shagbark hickory, striped maple, witch hazel, cornflower, Christmas fern, Bellport, gree ash, violet, wood nettle			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Small pools, coarse woody debris, scattered leaf packs			
Aquatic Organisms Observed (list): Invertebrates, crayfish			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): none			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

**Waterbody ID:**

shia410

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

UNT to Warwick Run; stream continues out of the corridor in both directions. The channel is braided upstream of centerline; high gradient stream with flashy high flows. Bank instability in the form of loose rocks and soil, exposed roots present and to be expected.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low







Waterbody SHIA410 facing north upstream



Waterbody SHIA410 facing south downstream





Waterbody SHIA410 facing east across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Warwick Run	
Waterbody ID: shia411		Date: 6/10/2016	
State: Virginia	County: Highland	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 5 photos			
Tract Number(s): access road 06-001-B001.AR1		Nearest Milepost: 85.1	Associated Wetland ID(s): whia409
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 14.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 1.25 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 20.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 12.0 ft.	Width of Waterbody - Water Edge to Water Edge: 12.0 ft.	Depth of Water: <i>(Approx.)</i> 0.40 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.0 fps	Bank height Right: 4.5 ft. Left: 3.5 ft.
Bank slope Right: 85 degrees Left: 80 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks show signs of instability in the form of loose rock/soil and exposed roots; consider normal for stream with moderately steep gradient			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      50%      35%      5%      5%      5%      _____%			
Width of Riparian Zone: 80 ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 12.0 in.      1.5 in.		
Dominant Bank Vegetation (list): Sugar maple, white oak, black locust, basswood, ironwood, hydrangea, hickory, autumn olive, blackberry, poison ivy, Virginia creeper, grape, Dutchman's pipe, wood nettle, foamflower, wood aster, violet, buttercup			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, scattered pools, coarse woody debris, wrack piles			
Aquatic Organisms Observed (list): Caddisfly, mayfly, minnow, scud			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Ford crossing for decommissioned dirt road; no culvert or bridge; vehicle traffic is historic – 20 years or more.			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

Waterbody ID:

shia411

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream continues out of access road corridor in both directions; moderately steep gradient stream; no culvert or bridge present; road is decommissioned with no vehicular traffic in over 20 years; saturated PEM seep wetland located in adjacent historic overflow channel; mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)

**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low

SHIA411  
PERENNIAL  
STREAM

See SHIA408

Mature 2nd  
growth mixed  
HWS forest  
with hemlock  
throughout


NO CULVERT  
NO BRIDGE

WITIA409  
PIEM

SB  
25'  
C  
25'  
SB

N ↑

X = DATA POINTS





Waterbody SHIA411 facing north upstream



Waterbody SHIA411 facing south downstream





Waterbody SHIA411 scouring facing west across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Lick Draft	
Waterbody ID: shia409		Date: 5/7/2016	
State: Virginia	County: Highland	Company: NRG- ERM	Crew Member Initials: GB, SA, AS
Photos: 5 Photos			
Tract Number(s): 06-001-B001 - GWNF		Nearest Milepost: 85.4	Associated Wetland ID(s): whia407; whia408
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 15. ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
OHWM Height: 1.25 ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: 25.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 11.0 ft.	Width of Waterbody - Water Edge to Water Edge: 13.0 ft.	Depth of Water: <i>(Approx.)</i> 0.75 ft.
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 2.0 fps	Bank height Right: 5.0 ft. Left: 4.5 ft.
N/A <input type="checkbox"/>		Bank slope Right: 60 degrees Left: 70 degrees	
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks exhibit instability in places in the form of loose rock/soil and exposed roots; would consider normal for stream of this gradient with flashy high flows			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input checked="" type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____ %      5 %      50 %      30 %      10 %      _____ %      5 %      _____ %			
Width of Riparian Zone: 150 ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 13.0 in.      1.0 in.      -		
Dominant Bank Vegetation (list): Northern red oak, red maple, sugar maple, hemlock, white oak, yellow poplar, sweet birch, hydrangea, witch hazel, ironwood, wood nettle, starwort, violet, Christmas fern, wood fern			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Isolated step pools, occasional leaf packs, woody debris, overhanging roots, riffles			
Aquatic Organisms Observed (list): Invertebrates, salamander, crayfish			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

**Waterbody ID:**

shia409

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream continues out of corridor in both directions; moderately steep gradient mountain stream with flashy high flows – as a result bank instability is present in places in the form of loose rock/soil and exposed roots. Saturated PFO seep wetlands whia407 & whia408 are located in swales along toe of slope above stream; whia407 receives hydrology from seep phia405 & spring phia406 – outflow from this feature has subterranean connection to stream outside corridor; whia408 receives hydrology from spring phia407 – outflow from this feature has direct surface connection to stream within the corridor.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)

**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low

↑ N

SB

150'

150' F

X = DATA POINTS

Spring phi A 406


WHIA 408 PFO

SEEP PHIA 405

WHIA 407 PFO

SHIA 409 PERENNIAL STREAM

Mature 2nd growth mixed hardwoods with strong hemlock element & occasional white pine







Waterbody SHIA409 facing north upstream



Waterbody SHIA409 facing south downstream



Waterbody SHIA409 facing east across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Lick Draft	
Waterbody ID: shia408		Date: 5/4/2016	
State: Virginia	County: Highland	Company: NRG - ERM	Crew Member Initials: GB, SA
Photos: 5 photos			
Tract Number(s): 06-001-B001 - GWNF		Nearest Milepost: 85.5	Associated Wetland ID(s): whia406
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 15.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 1.5 ft.		<input checked="" type="checkbox"/> Clear line on bank <input checked="" type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 20.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 10.0 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> 13.0 ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> 0.75 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> 1.5 fps N/A <input type="checkbox"/>	Bank height Right: 5.0 ft. Left: 5.0 ft.	Bank slope Right: 75 degrees Left: 85 degrees
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks exhibit instability in places; loose soil and rocks, exposed roots; normal for higher gradient streams			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input checked="" type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____ %      10 %      60 %      15 %      10 %      _____ %      5 %      _____ %			
Width of Riparian Zone: 100 ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
Avg. DBH of Dominants: <i>(approx.)</i> 14.0 in.      1.5 in.      -			
Dominant Bank Vegetation (list): Hemlock, yellow poplar, white pine, shagbark hickory, sugar maple, red maple, striped maple, sweet birch, witch hazel, mountain laurel, wood aster, violet, hay scented fern, miter box, trillium, wood fern			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Coarse woody debris, scattered small pools, overhanging roots, riffles			
Aquatic Organisms Observed (list): Minnows, invertebrates, water striders, frog			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Old road bed on west side of stream			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

**Waterbody ID:**

shia408

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream continues out of corridor in both directions; moderately steep gradient stream showing signs of bank instability in places as evidenced by loose rock/soil and exposed roots – consider normal for a stream of this gradient; paralleled by an old road bed on west side; spring fed PFO wetland whia406 has direct hydrologic connection; flows through mature second growth mixed hardwoods with white pine and hemlock. There is a proposed access road on east side; no road exists on that side of stream.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low





Waterbody SHIA408 facing north upstream



Waterbody SHIA408 facing south downstream





Waterbody SHIA408 facing east across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Muddy Run	
Waterbody ID: sbaa008		Date: 7/1/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 3 photos			
Tract Number(s): 36-016 – GWNF; access road 36-014.AR2		Nearest Milepost: 93.6	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 2.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.50 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 10.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1.0 ft.	Width of Waterbody - Water Edge to Water Edge: 1.5 ft.	Depth of Water: <i>(Approx.)</i> 0.25 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.0 fps	Bank height Right: 6.0 ft. Left: 2.5 ft.
Bank slope Right: 55 degrees Left: 60 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks are road cut and road base			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____ %      _____ %      10 %      30 %      25 %      25 %      10 %      _____ %			
Width of Riparian Zone: _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 14.0 in.      1.5 in.      -		
Dominant Bank Vegetation (list): Chestnut oak, sweet birch, yellow poplar, black locust, red maple, mountain laurel, minniebush, colts foot, Japanese stilt grass, crown vetch, milkweed, Christmas fern			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs			
Aquatic Organisms Observed (list): caddisfly			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Culvert crossing for existing road, confined to ditch upstream of culvert			
Tributary is: <i>(check one)</i> <input type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input checked="" type="checkbox"/> Manipulated			



Waterbody ID:

sbaa008

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream begins within ditch at road cut seep pbaa004; passes under existing gravel road via 18" corrugated metal culvert; downstream continues out of access road survey corridor where flow becomes subterranean. Mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low





Waterbody SBAA008 facing south upstream



Waterbody SBAA008 facing north downstream





Waterbody SBAA008 facing east across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Muddy Run	
Waterbody ID: sbaa009		Date: 7/1/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 3 photos			
Tract Number(s): 36-016 – GWNF; access road 36-014.AR2		Nearest Milepost: 93.6	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 2.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.50 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 6.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1.0 ft.	Width of Waterbody - Water Edge to Water Edge: 1.5 ft.	Depth of Water: <i>(Approx.)</i> 0.25 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.75 fps	Bank height Right: 3.5 ft. Left: 2.0 ft.
Bank slope Right: 60 degrees Left: 60 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks are road cut and road base			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      10%      35%      30%      15%      10%      _____%			
Width of Riparian Zone: _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 13.0 in.      1.0 in.      -		
Dominant Bank Vegetation (list): Northern red oak, white oak, sugar maple, black gum, striped male, scarlet oak, black locust, blackberry, Christmas fern, golden ragwort, bush clover, white snakeroot, jewel weed, colts foot			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs			
Aquatic Organisms Observed (list): caddisfly			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Culvert crossing for existing road, confined to ditch upstream of culvert			
Tributary is: <i>(check one)</i> <input type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input checked="" type="checkbox"/> Manipulated			

Waterbody ID:

sbaa009

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream begins within ditch at road cut seep pbaa005; passes under existing gravel road via 18" corrugated metal culvert; downstream continues out of access road survey corridor where flow becomes subterranean. Mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low







Waterbody SBAA009 facing southwest upstream



Waterbody SBAA009 facing northeast downstream





Waterbody SBAA009 facing southeast across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Muddy Run	
Waterbody ID: sbaa010		Date: 7/1/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 3 photos			
Tract Number(s): 36-016 – GWNF; access road 36-014.AR2		Nearest Milepost: 93.6	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 2.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.50 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 10.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1.5 ft.	Width of Waterbody - Water Edge to Water Edge: 1.5 ft.	Depth of Water: <i>(Approx.)</i> 0.25 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.75 fps	Bank height Right: 1.5 ft. Left: 8.0 ft.
Bank slope Right: 60 degrees Left: 50 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks are road cut and road base			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      20%      40%      20%      10%      10%      _____%			
Width of Riparian Zone: _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 13.0 in.      1.0 in.      -		
Dominant Bank Vegetation <i>(list)</i> : Northern red oak, white oak, sugar maple, black gum, striped male, scarlet oak, black locust, blackberry, Christmas fern, golden ragwort, bush clover, white snakeroot, jewel weed, colts foot			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs			
Aquatic Organisms Observed <i>(list)</i> : caddisfly			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Confined to ditch along existing road			
Tributary is: <i>(check one)</i> <input type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input checked="" type="checkbox"/> Manipulated			

Waterbody ID:

sbaa010

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream begins within ditch at nick point seep pbaa006; does not cross road; downstream continues out of access road survey corridor where flow becomes subterranean. Mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low







Waterbody SBAA010 facing northeast upstream



Waterbody SBAA010 facing southwest downstream





Waterbody SBAA010 facing southeast across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Muddy Run	
Waterbody ID: sbaa011		Date: 7/1/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 3 photos			
Tract Number(s): 36-016 – GWNF; access road 36-014.AR2		Nearest Milepost: 93.6	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 2.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.50 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 10.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1.5 ft.	Width of Waterbody - Water Edge to Water Edge: 1.5 ft.	Depth of Water: <i>(Approx.)</i> 0.25 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.50 fps	Bank height Right: 10.0 ft. Left: 3.0 ft.
Bank slope Right: 75 degrees Left: 45 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks are road cut and road base			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____ %      _____ %      5 %      25 %      35 %      20 %      15 %      _____ %			
Width of Riparian Zone: _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 10.0 in.      1.5 in.      -		
Dominant Bank Vegetation (list): Northern red oak, hickory, sweet birch, sugar maple, black cherry, scarlet oak, black locust, garlic mustard, Japanese stilt grass, jewel weed, white snake root, New York fern, violet, blackberry			
Aquatic Habitats (ex: submerged or emergent aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, emergent vegetation			
Aquatic Organisms Observed (list): caddisfly			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Culvert crossing for existing road, confined to ditch upstream of culvert			
Tributary is: <i>(check one)</i> <input type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input checked="" type="checkbox"/> Manipulated			

Waterbody ID:

sbaa011

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream begins well outside proposed access road survey corridor on a rocky slope at spring pbaa007; follows ditch along existing road for 120 feet before passing under existing gravel road via 18" corrugated metal culvert; downstream continues out of access road survey corridor where most flow becomes subterranean; remaining flow enters a small, excavated and bermed open water body approximately 12 feet in diameter on a decommissioned road bed outside survey corridor. Mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)

**Stream Quality <sup>a</sup>:**


(check one)

High

Moderate

Low







Waterbody SBA011 facing northeast upstream



Waterbody SBA011 facing southeast downstream





Waterbody SBAA011 facing southeast across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Laurel Run	
Waterbody ID: sbaa004		Date: 6/21/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 3 photos			
Tract Number(s): 36-016 - GWNF		Nearest Milepost: 94.1	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 7.0 ft.  Height: 1.0 ft. N/A <input type="checkbox"/>		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining  <input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 12.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 4.0 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> 6.0 ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> 0.50 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> 0.75 fps N/A <input type="checkbox"/>	Bank height Right: 3.0 ft. Left: 2.5 ft.	Bank slope Right: 70 degrees Left: 60 degrees
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks appear stable for a stream of moderate gradient; small undercut areas on outside of bends considered normal.			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____%      55%      25%      10%      5%      5%      _____%			
Width of Riparian Zone: 60 ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: 12.0 in. <input checked="" type="checkbox"/> Saplings/Shrubs: 1.5 in. <input checked="" type="checkbox"/> Herbs: - Avg. DBH of Dominants: <i>(approx.)</i>		
Dominant Bank Vegetation (list): White oak, black gum, scarlet oak, chestnut oak, sassafras, sweet birch, white pine, witch hazel, mountain laurel, rhododendron, wood fern, Indian cucumber root, violet, Christmas fern			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, scattered small pools, overhanging roots, woody debris, wrack piles			
Aquatic Organisms Observed (list): Invertebrates – caddisfly, crane fly, mayfly; crayfish			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None recent; there is a very old road bed on the west side that has grown completely shut			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			



Waterbody ID:

sbaa004

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Perennial stream of moderate gradient with a meandering channel; there is a small braid at the upstream edge of the corridor. Mature second growth mixed hardwood forest with scattered white pine.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low





Waterbody sbaa004 facing southwest downstream



Waterbody sbaa004 facing northeast upstream





Waterbody sbaa004 facing northwest across



# Open Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Unnamed Pond	
Waterbody ID: obaa003		Date: 10/27/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, AS
Photos: 3 photos			
Tract Number(s): 36-016 - GWNF		Nearest Milepost: 96.3	Associated Wetland ID(s): none
Survey Type: <small>(check one)</small> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Waterbody Type: <small>(check one)</small> <input type="checkbox"/> Stock Pond <input type="checkbox"/> Natural Pond <input type="checkbox"/> Lake <input type="checkbox"/> Reservoir <input checked="" type="checkbox"/> Impoundment <input type="checkbox"/> Oxbow <input type="checkbox"/> Other:			
Hydrologic Regime: <input type="checkbox"/> Permanently Flooded <input checked="" type="checkbox"/> Semipermanently Flooded <input type="checkbox"/> Seasonally Flooded <input type="checkbox"/> Temporarily Flooded			
OHWM Height: <u>3.0</u> ft.	OHWM Indicator: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
Depth of Water: <u>2.0</u> ft. N/A <input type="checkbox"/>	Bank height (average): <u>5.0</u> ft.	Bank slope (average): <u>70</u> degrees	
Qualitative Attributes			
Water Appearance: <small>(check one)</small> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <small>(check all that apply)</small> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      _____%      _____% <u>20</u> % <u>60</u> % <u>20</u> %      _____%			
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>	Vegetative Layers: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <small>(approx.)</small> <u>14.0</u> in. <u>1.0</u> in.		
Dominant Bank Vegetation <i>(list)</i> : Scarlet oak, sugar maple, red maple, black gum, witch hazel, huckleberry, Minnie bush, blueberry, yellow poplar, zigzag g oldenrod, rough leaf goldenrod, mountain laurel, spotted wintergreen			
Aquatic Habitats <small>(ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.)</small> : Pool, coarse woody debris			
Aquatic Organisms Observed <i>(list)</i> : none			
T&E Species Observed <i>(list)</i> : none			
Disturbances <small>(ex: livestock access, manure in waterbody, waste discharge pipes)</small> : None observed			
Waterbody is: <small>(check one)</small> <input type="checkbox"/> Natural <input checked="" type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Waterbody Quality <sup>a</sup> : <small>(check one)</small> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

obaa003

<sup>a</sup> **High Quality:** Natural, natural bank vegetation around entire waterbody; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or bank vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Excavated and beamed small, artificial impoundment located in a draw; filled by sheet flow; overflow to ephemeral stream sbaa014; mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point locations, survey boundary, and IDs of associated features)







obaa003 facing southeast



obaa003 facing southwest





obaa003 facing northwest

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: Campbell Run		Waterbody ID: sbaa014
Date: 10/27/2016				
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, AS	Photos: 3 photos
Tract Number(s): 36-016. GWNF		Nearest Milepost: 96.3	Associated Wetland ID(s): none	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 2.0 ft.		OHWM Indicator: <i>(check all that apply)</i>		
Height: 0.5 ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 5.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1.0 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> _____ ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> _____ ft.	
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _____ fps N/A <input checked="" type="checkbox"/>	Bank height Right: 2.5 ft. Left: 3.0 ft.	Bank slope Right: 40 degrees Left: 60 degrees	
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): No evidence of bank instability observed				
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _____ %      _____ %      30 %      10 %      15 %      25 %      20 %      _____ %				
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> 14.0 in.      1.0 in.      _____ in.			
Dominant Bank Vegetation ( <i>list</i> ): Scarlet oak, sugar maple, red maple, black gum, witch hazel, huckleberry, Minnie bush, blueberry, yellow poplar, zigzag g oldenrod, rough leaf goldenrod, mountain laurel, spotted wintergreen				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs				
Aquatic Organisms Observed ( <i>list</i> ): none				
T&E Species Observed ( <i>list</i> ): none				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): none				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				

Waterbody ID:

sbaa014

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Begins as outflow/overflow from impoundment obaa003 within the survey corridor; downstream continues out of the survey corridor; bed/bank/OHWM weakly developed within the corridor becoming more distinct outside the survey corridor.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)


High

Moderate

Low









sbaa014 facing west upstream



sbaa014 facing east downstream





sbaa014 facing north across

# Open Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Unnamed Pond	
Waterbody ID: obaa001		Date: 6/25/2016	
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Photos: 1 Photo			
Tract Number(s): 36-016 – GWNF; access road 36-016.AR1		Nearest Milepost: 96.5	Associated Wetland ID(s): none
Survey Type: <small>(check one)</small> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Waterbody Type: <small>(check one)</small> <input type="checkbox"/> Stock Pond <input type="checkbox"/> Natural Pond <input type="checkbox"/> Lake <input type="checkbox"/> Reservoir <input checked="" type="checkbox"/> Impoundment <input type="checkbox"/> Oxbow <input type="checkbox"/> Other:			
Hydrologic Regime: <input type="checkbox"/> Permanently Flooded <input checked="" type="checkbox"/> Semipermanently Flooded <input type="checkbox"/> Seasonally Flooded <input type="checkbox"/> Temporarily Flooded			
OHWM Height: <u>2.0</u> ft.		OHWM Indicator: <small>(check all that apply)</small>	
		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input checked="" type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Depth of Water: <u>1.5</u> ft. N/A <input type="checkbox"/>		Bank height (average): <u>3.5</u> ft.	
		Bank slope (average): <u>70</u> degrees	
Qualitative Attributes			
Water Appearance: <small>(check one)</small> <input type="checkbox"/> No water <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <small>(check all that apply)</small> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      _____%      _____% <u>30</u> % <u>40</u> % <u>30</u> %      _____%			
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>		Vegetative Layers: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs	
		Avg. DBH of Dominants: <small>(approx.)</small> <u>12.0</u> in. <u>1.75</u> in.	
Dominant Bank Vegetation <i>(list)</i> : Scarlet oak, sweet birch, chestnut oak, yellow poplar, black locust, grape, red maple, blackberry, fleabane, Japanese stilt grass, white snakeroot, Virginia creeper			
Aquatic Habitats <small>(ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools, etc.):</small> pool			
Aquatic Organisms Observed <i>(list)</i> : Tadpoles, salamander			
T&E Species Observed <i>(list)</i> : none			
Disturbances <small>(ex: livestock access, manure in waterbody, waste discharge pipes)</small> : Sediment run-off from adjacent road			
Waterbody is: <small>(check one)</small> <input type="checkbox"/> Natural <input checked="" type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Waterbody Quality <sup>a</sup> : <small>(check one)</small> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			



Waterbody ID:

obaa001

<sup>a</sup> **High Quality:** Natural, natural bank vegetation around entire waterbody; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or bank vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Excavated impoundment adjacent to existing forest service road; likely created for amphibian habitat; there are additional impoundments down-slope of this one which are outside the access road survey corridor. Receives sheet flow from adjacent roadbeds and slope. Mature second growth mixed hardwood forest.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point locations, survey boundary, and IDs of associated features)





Open waterbody OBAA001 facing south

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Cowpasture River		Waterbody ID: sbaa005
Date: 6/24/2016				
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO	Photos: 3 Photos
Tract Number(s): 36-016 - GWNF		Nearest Milepost: 98.3		Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 11.0 ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
OHWM Height: 1.5 ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 20.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 6.5 ft.	Width of Waterbody - Water Edge to Water Edge: 10.0 ft.	Depth of Water: <i>(Approx.)</i> 1.25 ft.	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.25 fps		Bank slope Right: 60 degrees Left: 70 degrees
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Bedrock <input checked="" type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      20 %      10 %      30 %      30 %      10 %      _____ %      _____ %      _____ %				
Width of Riparian Zone: 50 ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> 12.0 in.      1.5 in.      -		
Dominant Bank Vegetation <i>(list)</i> : White oak, sugar maple, white pine, chestnut oak, pignut hickory, black gum, red maple, witch hazel, blackhaw, huckleberry, grape, cinquefoil, panic grass, wild rye, violet, woodland sedge				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Step pools, coarse woody debris, wrack piles				
Aquatic Organisms Observed <i>(list)</i> : Invertebrates – mayfly, caddisfly; crayfish				
T&E Species Observed <i>(list)</i> : none				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>3</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

sbaa005

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Moderately steep gradient perennial stream; continues out of the survey corridor in both directions; banks exhibit no signs of instability; slopes above bank are steep; mature second growth mixed hardwood forest with a white pine element.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SBAA005 facing east upstream



Waterbody SBAA005 facing northwest downstream



Waterbody SBAA005 facing north across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline	Waterbody Name: UNT to Cowpasture River	Waterbody ID: sbaa006	Date: 6/24/2016
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO
Tract Number(s): 36-016 - GWNF		Nearest Milepost: 98.9	Associated Wetland ID(s): None
Survey Type: <small>(check one)</small> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <small>(check one)</small> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <small>(check one)</small> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>4.0</u> ft.  Height: <u>0.50</u> ft. N/A <input type="checkbox"/>	OHWM Indicator: <small>(check all that apply)</small> <input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input checked="" type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank: <u>12.0</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>3.5</u> ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> <u>3.5</u> ft.	Depth of Water: <small>(Approx.)</small> N/A <input type="checkbox"/> <u>0.25</u> ft.
Sinuosity: <small>(check one)</small> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering	Water velocity: <small>(Approx.)</small> <u>0.75</u> fps N/A <input type="checkbox"/>	Bank height Right: <u>6.0</u> ft. Left: <u>6.0</u> ft.	Bank slope Right: <u>75</u> degrees Left: <u>60</u> degrees
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): No evidence of bank instability observed			
Qualitative Attributes			
Water Appearance: <small>(check one)</small> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <small>(check all that apply)</small> % of Substrate:    _____%    _____% <u>10</u> % <u>40</u> % <u>30</u> % <u>10</u> % <u>10</u> %    _____%			
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>	Vegetative Layers: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Trees: <u>13.0</u> in. <input checked="" type="checkbox"/> Saplings/Shrubs: <u>1.75</u> in. <input checked="" type="checkbox"/> Herbs:    _____		
Dominant Bank Vegetation (list): White oak, black gum, shagbark hickory, northern red oak, pignut hickory, white pine, sugar maple, witch hazel, huckleberry, panic grass, wood rush, cinquefoil, woodland sedge, violet, wild yams, spotted wintergreen			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, coarse woody debris			
Aquatic Organisms Observed (list): none			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent			
Tributary is: <small>(check one)</small> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			



Waterbody ID:

sbaa006

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Weakly intermittent stream of moderately steep gradient; banks not well defined; slopes above steep; continues out of the survey corridor in both directions; mature second growth mixed hardwood forest with white pine element.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)

**Stream Quality <sup>a</sup>:**


(check one)

High

Moderate

Low







Waterbody SBAA006 facing north upstream



Waterbody SBAA006 facing south downstream





Waterbody SBAA006 facing west across

# Linear Waterbody Data Sheet

Survey Description						
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Cowpasture River		Waterbody ID: sbaa007		Date: 6/24/2016
State: Virginia	County: Bath	Company: NRG/ERM	Crew Member Initials: GB, KO	Photos: 5 photos		
Tract Number(s): 36-016 – GWNF; red tract polygon with 36-029 – 36-0 labels within polygon		Nearest Milepost: 98.95		Associated Wetland ID(s): Maybe within no access tract		
Survey Type: <small>(check one)</small> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:						
Physical Attributes						
Stream Classification: <small>(check one)</small> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial						
Waterbody Type: <small>(check one)</small> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:						
OHWM Width: <u>9.0</u> ft.  Height: <u>1.25</u> ft. N/A <input type="checkbox"/>		OHWM Indicator: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input checked="" type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change				
Width of Waterbody - Top of Bank to Top of Bank: <u>20.0</u> ft.		Width of Waterbody - Toe of Slope to Toe of Slope: <u>4.5</u> ft.		Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> <u>6.5</u> ft.		Depth of Water: <small>(Approx.)</small> N/A <input type="checkbox"/> <u>0.75</u> ft.
Sinuosity: <small>(check one)</small> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <small>(Approx.)</small> <u>1.0</u> fps N/A <input type="checkbox"/>		Bank height Right: <u>10.0</u> ft. Left: <u>3.0</u> ft.		Bank slope Right: <u>70</u> degrees Left: <u>90</u> degrees
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): Banks exhibit undercutting on outside of meanders; slope slumping off in places above bank; see photos.						
Qualitative Attributes						
Water Appearance: <small>(check one)</small> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:						
Substrate: <small>(check all that apply)</small> % of Substrate:      _____%      _____% <u>10</u> %      _____% <u>60</u> % <u>15</u> % <u>15</u> %      _____%      _____%						
Width of Riparian Zone: N/A <input type="checkbox"/> <u>150</u> ft.		Vegetative Layers: <small>(check all that apply)</small> <input checked="" type="checkbox"/> Trees: <u>13.0</u> in. <input checked="" type="checkbox"/> Saplings/Shrubs: <u>1.75</u> in. <input checked="" type="checkbox"/> Herbs:      - Avg. DBH of Dominants: <small>(approx.)</small>				
Dominant Bank Vegetation <small>(list)</small> : White oak, black gum, shagbark hickory, northern red oak, pignut hickory, white pine, sugar maple, witch hazel, blackhaw, panic grass, wood rush, woodland sedge, wing stem, Japanese stilt grass, golden ragwort						
Aquatic Habitats <small>(ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools)</small> : Leaf packs, coarse woody debris, overhanging roots, pools, riffles						
Aquatic Organisms Observed <small>(list)</small> : Water striders, caddisfly, crayfish						
T&E Species Observed <small>(list)</small> : none						
Disturbances <small>(ex: livestock access, manure in waterbody, waste discharge pipes)</small> : None apparent						
Tributary is: <small>(check one)</small> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated						



Waterbody ID:

sbaa007

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Intermittent stream of moderately steep gradient; banks undercut at outside meanders; slopes above steep with some slumping due to undercut; continues out of the survey corridor in both directions; mature second growth mixed hardwood forest with white pine element.

Only a portion of stream could be delineated as the majority is on a private no access tract owned by Fort Lewis.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low



Mature 2nd growth  
mixed WNS with white  
pine element  
throughout

SBAA007  
Intermittent  
Stream

NO ACCESS  
TRACT

X DATA  
Pt.

NOT  
MAPPED

↑N

150'  
E1

150'  
SB

SB

SB



Waterbody SBAA007 facing north upstream



Waterbody SBAA007 facing south downstream





Waterbody SBAA007 facing west across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Gibson Hollow	
Waterbody ID: sbaa003		Date: 5/9/2016	
State: Virginia	County: Bath	Company: NRG-ERM	Crew Member Initials: GB, SA, LC
Photos: 3 photos			
Tract Number(s): 36-016 - GWNF		Nearest Milepost: 99.4	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 3.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
OHWM Height: 0.33 ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 6.0 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 2.0 ft.	Width of Waterbody - Water Edge to Water Edge: 1.5 ft.	Depth of Water: <i>(Approx.)</i> 0.20 ft.
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.15 fps	Bank height: Right: 4.0 ft. Left: 3.0 ft.
Bank slope: Right: 60 degrees Left: 65 degrees			
Analysis of Bank Stability (i.e. root structure, vegetation, substrate characteristics): There is no evidence of bank instability.			
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      _____%      35%      20%      10%      35%      _____%			
Width of Riparian Zone: _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 11.0 in.      2.0 in.      -		
Dominant Bank Vegetation (list): Northern red oak, white oak, white pine, red maple, hop hornbeam, chestnut oak, hawthorne, violet, wild oat grass, woodland sedge, wood rush			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, coarse woody debris			
Aquatic Organisms Observed (list): none			
T&E Species Observed (list): none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			

**Waterbody ID:**

sbaa003

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Begins as outflow from seep pbaa002; flow alternates between primarily subterranean and primarily surface. Surrounding area is mature second growth mixed hardwoods. Seep and stream are just outside and then roughly parallel to the edge of survey corridor. There is an intermittent stream and a perennial stream associated with sbaa003; however they are over the GWNF boundary in a permission denied tract – 36-032.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)


**Stream Quality <sup>a</sup>:**

(check one)

High

Moderate

Low





Waterbody SBAA003 facing south upstream



Waterbody SBAA003 facing north downstream





Waterbody SBAA003 facing east across

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: Gibson Hollow		Waterbody ID: sbaa019
Date: 10/29/2016				
State: Virginia	County: Bath	Company: NRG - ERM	Crew Member Initials: GB, AS	Photos: 3 photos
Tract Number(s): 36-029		Nearest Milepost: 99.3		Associated Wetland ID(s): wbaa005
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes <input checked="" type="checkbox"/>				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: _____ ft. 9.0		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
OHWM Height: _____ ft. 1.25		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: _____ ft. 15.0	Width of Waterbody - Toe of Slope to Toe of Slope: _____ ft. 6.0	Width of Waterbody - Water Edge to Water Edge: _____ ft. 5.0	Depth of Water: <i>(Approx.)</i> _____ ft. 0.50	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> _____ fps 0.33		Bank height Right: _____ ft. 2.0 Left: _____ ft. 3.0
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		Bank slope Right: _____ degrees 35 Left: _____ degrees 90
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input checked="" type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _____ %      _____ %      10 %      40 %      30 %      10 %      10 %      15 %      _____ %				
Width of Riparian Zone: _____ ft. 120		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> _____ in.      12.0      _____ in.      1.5		
Dominant Bank Vegetation <i>(list)</i> : northern red oak, white oak, hop hornbeam, red maple, black gum, white pine, shagbark hickory, wild rye, Japanese stilt grass, deer tongue grass, mountain brome, golden ragwort, wood aster, violet				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): coarse woody debris, leaf packs, pools, scattered emergent vegetation				
Aquatic Organisms Observed <i>(list)</i> : Water striders, caddisfly, crayfish				
T&E Species Observed <i>(list)</i> : none				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Dirt ATV road crossing – no culvert or bridge present				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>3</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

sbaa019

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Continues out of the survey corridor in both directions. PFO wetland wbaa005 present on both sides of stream; sbaa003 flow enters steam via wbaa005; sbaa003 loses channel and ends within wetland.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







**sbaa019 facing north upstream**



**sbaa019 facing south downstream**





sbaa019 facing east across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Barn Lick Branch	
Waterbody ID: SAUA436		Date: 9/27/2016	
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, SA
Photos: 01-03			
Tract Number(s): 07-001-A008		Nearest Milepost: 111.25	Associated Wetland ID(s): WAUB102
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 8.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 1.0 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 10 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 3.0 ft.	Width of Waterbody - Water Edge to Water Edge: 6.0 ft.	Depth of Water: <i>(Approx.)</i> 0.5 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.5 fps	Bank height Right: 3.5 ft. Left: 2 ft.
N/A <input type="checkbox"/>		Bank slope Right: 90 degrees Left: 80 degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i>			
% of Substrate:      _____%      _____%      5%      25%      40%      30%      _____%      _____%			
Width of Riparian Zone: >70 ft.		Vegetative Layers: <i>(check all that apply)</i>	
N/A <input type="checkbox"/>		<input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input type="checkbox"/> Herbs	
		Avg. DBH of Dominants: <i>(approx.)</i> 10 in.      2 in.	
Dominant Bank Vegetation <i>(list)</i> : White oak, white pine, musclewood			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Cobble, roots along bank, debris pile			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Selectively logged			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>3</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Strong sinuosity, weak riffle pool, strong grade control, well developed bars and benches, debris piles. Banks undercut and unstable on outside of bends. Previously named saub108.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA436 facing north upstream



Waterbody SAUA436 facing west across





Waterbody SAUA436 facing south downstream

Linear Waterbody Data Sheet

<b>Survey Description</b>			
Project Name: <i>ACP</i>	Waterbody Name: <i>Braley Branch</i>	Waterbody ID: <i>sauP003. i</i>	Date: <i>9/27/16</i> <i>19 Aug 2015</i>
State: <i>VA</i>	County/Parish: <i>Augusta</i>	Company: <i>ESI ERM</i>	Crew Member Initials: <i>KWM, GSM GB, AS</i>
Photos: <i>N, S, E</i>		Tract Number(s): <i>07-001-A010, 07-001-A009</i>	Nearest Milepost: <i>116.5</i>
Associated Wetland ID(s): <i>None</i>		Survey Type: (check one) <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:	
<b>Physical Attributes</b>			
Stream Classification: (check one) <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: (check one) <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <i>14</i> ft.	OHWM Indicator: (check all that apply) <input checked="" type="checkbox"/> Clear line on bank <input checked="" type="checkbox"/> Shelving <input checked="" type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining	Height: <i>2.0</i> ft.	
N/A <input type="checkbox"/>	<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input checked="" type="checkbox"/> Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank: <i>24</i> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <i>8</i> ft.	Width of Waterbody - Water Edge to Water Edge: <i>N/A</i>	Depth of Water: (Approx.) <i>N/A</i> ft.
Sinuosity: (check one) <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: (Approx.) <i>N/A</i> fps	Bank height Right: <i>4</i> ft. Left: <i>5.0</i> ft.	Bank slope Right: <i>80</i> <sup>35</sup> degrees Left: <i>30</i> <sup>90</sup> degrees
<b>Qualitative Attributes</b>			
Water Appearance: (check one) <input checked="" type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: (check all that apply) <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/clay <input type="checkbox"/> Organic <input type="checkbox"/> Other: % of Substrate: _____% _____% <i>50</i> % <i>40</i> % _____% <i>10</i> % _____% _____%			
Width of Riparian Zone: <i>100</i> ft.	Vegetative Layers: (check all that apply) <input checked="" type="checkbox"/> Trees: <i>5</i> in. <input checked="" type="checkbox"/> Saplings/Shrubs: <i>2</i> in. <input checked="" type="checkbox"/> Herbs: <i>N/A</i> in.		
N/A <input type="checkbox"/>			
Dominant Bank Vegetation (list): <i>Acer rubrum, Acer saccharum, Hamamelis virginiana, Microstegium vimineum, Lonicera japonica</i>			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): <i>Pools, intermittent flow, woody debris, root mats</i>			
Aquatic Organisms Observed (list): <i>None minnows, water striders, stonefly, water penny</i>			
T&E Species Observed (list): <i>None</i>			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): <i>Paralleled by existing road and wire fencing wrapped around cobble to limit bank erosion on outside of bend. Banks are severely undercut and unstable in outside bends.</i>			
Tributary is: (check one) <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality*: (check one) <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input checked="" type="checkbox"/> Low			


Waterbody ID:  
saup003 i

- High Quality: Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.
- Moderate Quality: Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.
- Low Quality: Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Notes:

changed ID from saup003i to sau435

Waterbody Sketch (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





*Environmental Field Surveys*  
*Waterbody Photo Page*



**Waterbody sau435 facing north upstream.**



**Waterbody sau435 facing south downstream.**



*Environmental Field Surveys*  
*Waterbody Photo Page*



**Waterbody saua435 facing east across bank.**

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: Dowell's Draft		Waterbody ID: SAUA416
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, AS	Photos: SAUA416_001-004
Tract Number(s): 07-001		Nearest Milepost: 112	Associated Wetland ID(s): WAUC002	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: _16_ ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
Height: _2_ ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: _18_ ft.	Width of Waterbody - Toe of Slope to Toe of Slope: _12_ ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> _15_ ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> _0.8_ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _2_ fps N/A <input type="checkbox"/>	Bank height Right: _4_ ft. Left: _4_ ft.	Bank slope Right: _70_ degrees Left: _70_ degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _____%      _____% <u>60</u> % <u>40</u> %      _____%      _____%      _____%      _____%				
Width of Riparian Zone: N/A <input type="checkbox"/> <u>90</u> ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs			
	Avg. DBH of Dominants: <i>(approx.)</i> <u>14</u> in. <u>2</u> in.			
Dominant Bank Vegetation <i>(list)</i> : Eastern Hemlock, White Pine, White Oak, Violet, Red Maple, Christmas Fern				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Riffles and pools, downed logs in bed, Over hanging banks and roots				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Access road with a four foot diameter culvert				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA416

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

former sauc002 is now saua416

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA416 facing west upstream



Waterbody SAUA416 facing east downstream





Waterbody SAUA416 facing south across



Waterbody sau416 facing north upstream - culvert

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Dowell's Draft		Waterbody ID: SAUA417
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, AS	Photos: SAUA417_001-003
Tract Number(s): 07-001		Nearest Milepost: 112	Associated Wetland ID(s): WAUC002	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: _6_ ft.		OHWM Indicator: <i>(check all that apply)</i>		
Height: _0.5_ ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input checked="" type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: _6_ ft.	Width of Waterbody - Toe of Slope to Toe of Slope: _3_ ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> _6_ ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> _0.3_ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _0.5_ fps N/A <input type="checkbox"/>	Bank height Right: _4_ ft. Left: _10_ ft.	Bank slope Right: _60_ degrees Left: _70_ degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____% <u>5</u> % <u>5</u> % <u>10</u> % <u>80</u> %      _____%      _____%				
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> <u>12</u> in. <u>2</u> in.			
Dominant Bank Vegetation <i>(list)</i> : Christmas Fern, White Pine, Easter Hemlock, White Oak				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): None				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA417

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

saua417 was previously named sauc003.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA417 facing north upstream



Waterbody SAUA417 facing south downstream



Waterbody SAUA417 facing east across

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Dowell's Draft		Waterbody ID: SAUA418
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: SAUA418_001-003
Tract Number(s): 07-001		Nearest Milepost: 112	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: _ 8 _ ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
Height: _ 1 _ ft.		<input checked="" type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: _ 12 _ ft.	Width of Waterbody - Toe of Slope to Toe of Slope: _ 3 _ ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> _ 8 _ ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> _ 0.8 _ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _ 1.5 _ fps N/A <input type="checkbox"/>	Bank height Right: _ 4 _ ft. Left: _ 3 _ ft.	Bank slope Right: _ 70 _ degrees Left: _ 75 _ degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _ 80 _ %      _____ %      _____ %      _ 15 _ %      _ 5 _ %      _____ %      _____ %      _____ %				
Width of Riparian Zone: _ 30 _ ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs			
Avg. DBH of Dominants: <i>(approx.)</i> _ 12 _ in.      _ 2 _ in.				
Dominant Bank Vegetation <i>(list)</i> : White Pine, White Oak, Red Maple, Common Smilax, May-apple, Christmas fern, bedstraw				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Riffles and pools				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge) Stream runs through a culvert under an access road down stream				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA418

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

saua418 was previously named sauc004.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA418 facing north upstream



Waterbody SAUA418 facing south downstream



Waterbody SAUA418 facing west across





Waterbody sau418 facing south - culvert

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: East Branch Dowell's Draft	
Waterbody ID: SAUA420		Date: 9/20/2016	
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, AS
Photos: 01-03			
Tract Number(s): 07-001		Nearest Milepost: 117.3	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>10.0</u> ft.  Height: <u>1.5</u> ft. N/A <input type="checkbox"/>		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input checked="" type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: <u>12</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>3.0</u> ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> <u>6.0</u> ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> <u>0.5</u> ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> <u>1.5</u> fps N/A <input type="checkbox"/>	Bank height Right: <u>4</u> ft. Left: <u>4</u> ft.	Bank slope Right: <u>85</u> degrees Left: <u>85</u> degrees
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____% <u>30</u> % <u>35</u> % <u>25</u> % <u>10</u> %      _____%      _____%			
Width of Riparian Zone: <u>&gt;50</u> ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <u>13</u> in. <input checked="" type="checkbox"/> Saplings/Shrubs: <u>2</u> in. <input type="checkbox"/> Herbs		
Dominant Bank Vegetation <i>(list)</i> : White oak, sugar maple, musclewood			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Cobble, roots along bank, debris pile			
Aquatic Organisms Observed <i>(list)</i> : Mayfly, caddis fly			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Logging road, no culvert			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>3</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			



Waterbody ID:

SAUA420

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Moderate sinuosity, moderate riffle pool, strong grade control, well developed bars and benches, debris piles.

SAUA420 previously named SAUB110

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA420 facing east upstream



Waterbody SAUA420 facing north across





Waterbody SAUA420 facing west downstream

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Dowell's Draft		Waterbody ID: SAUA419
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: SAUA419_001-003
Tract Number(s): 07-001		Nearest Milepost: 113	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 7 ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
OHWM Height: 1.5 ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 15 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 3 ft.	Width of Waterbody - Water Edge to Water Edge: 5 ft.	Depth of Water: <i>(Approx.)</i> 1 ft.	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1 fps	Bank height Right: 5 ft. Left: 10 ft.	Bank slope Right: 60 degrees Left: 75 degrees
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _____%      _____%      20%      40%      40%      _____%      _____%      _____%				
Width of Riparian Zone: 20 ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs			
N/A <input type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> 12 in.      2 in.			
Dominant Bank Vegetation <i>(list)</i> : White Pine, White Oak, Red Maple, Post Oak, Mountain Laurel, River Oats, Poison Ivy				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Riffles and Pools, leaf packs				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				



Waterbody ID:

SAUA419

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream branches downstream and then quickly merges back into a single stream

saua419 was previously named sauc005

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA419 facing north upstream



Waterbody SAUA419 facing south downstream



Waterbody SAUA419 facing east across





Waterbody sau419 headcut



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Buckhorn Creek	
Waterbody ID: SAUA427e		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: SAUA427e_001-003			
Tract Number(s): 07-001		Nearest Milepost: 120.2	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>  2  </u> ft.  Height: <u>  0.5  </u> ft. N/A <input type="checkbox"/>		OHWM Indicator: <i>(check all that apply)</i> <input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: <u>  15  </u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>  1  </u> ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> <u>    </u> ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> <u>    </u> ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> <u>    </u> fps N/A <input checked="" type="checkbox"/>	Bank height Right: <u>  8  </u> ft. Left: <u>  4  </u> ft.	Bank slope Right: <u>  70  </u> degrees Left: <u>  40  </u> degrees
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> % of Substrate: <u>    </u> % <u>  10  </u> % <u>  80  </u> % <u>  10  </u> % <u>    </u> % <u>    </u> % <u>    </u> %			
Width of Riparian Zone: <u>  150  </u> ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> <u>  12  </u> in. <u>  2  </u> in.		
Dominant Bank Vegetation <i>(list)</i> : White Oak, White Pine, American Hornbeam, Red Maple, May-Apple, Violet, Smilax			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): None			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA427e

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream receives runoff from the nearby hillslope and from White Oak draft during flood events. Due to the high cobble content the OHWM is obscured.

saua427e was previously named sauc007.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA427e facing north upstream



Waterbody SAUA427e facing south downstream



Waterbody SAUA427e facing west across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: Buckhorn Creek	
Waterbody ID: SAUA427p		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: SAUA427p_001-003			
Tract Number(s): 07-001		Nearest Milepost: 120.2	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>20</u> ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
Height: <u>2.5</u> ft.		<input checked="" type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input checked="" type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: <u>25</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>8</u> ft.	Width of Waterbody - Water Edge to Water Edge: <u>10</u> ft.	Depth of Water: <i>(Approx.)</i> <u>1</u> ft.
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> <u>1.5</u> fps	Bank height Right: <u>3.5</u> ft. Left: <u>5.5</u> ft.
N/A <input type="checkbox"/>		Bank slope Right: <u>30</u> degrees Left: <u>90</u> degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____% <u>60</u> % <u>30</u> % <u>10</u> %      _____%      _____%      _____%			
Width of Riparian Zone: <u>150</u> ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs	
N/A <input type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> <u>10</u> in. <u>2</u> in.	
Dominant Bank Vegetation <i>(list)</i> : White Oak, White Pine, Sycamore, Red Maple, May-Apple, Violet, Smilax			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Deep pools and riffles, over hanging banks and roots, downed logs in stream bed, Strong grade control			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA427p

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream located a few hundred feet from a camp ground

saua427p was previously named sauc006

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA427p facing east upstream



Waterbody SAUA427p facing west downstream



Waterbody SAUA427p facing south across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Buckhorn Creek	
Waterbody ID: SAUA426		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: 01-03			
Tract Number(s): 07-001- AR466A		Nearest Milepost: 120.2	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>10.0</u> ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: <u>2.0</u> ft.		<input checked="" type="checkbox"/> Clear line on bank <input checked="" type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: <u>15</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>5.0</u> ft.	Width of Waterbody - Water Edge to Water Edge: <u>8.0</u> ft.	Depth of Water: <i>(Approx.)</i> <u>0.5</u> ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> <u>1.5</u> fps	Bank height Right: <u>6</u> ft. Left: <u>6</u> ft.
N/A <input type="checkbox"/>		Bank slope Right: <u>85</u> degrees Left: <u>85</u> degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i>			
% of Substrate:      _____%      _____% <u>45</u> % <u>30</u> % <u>15</u> % <u>10</u> %      _____%      _____%			
Width of Riparian Zone: <u>&gt;80</u> ft.		Vegetative Layers: <i>(check all that apply)</i>	
N/A <input type="checkbox"/>		<input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input type="checkbox"/> Herbs	
		Avg. DBH of Dominants: <i>(approx.)</i> <u>10</u> in. <u>2</u> in.	
Dominant Bank Vegetation <i>(list)</i> : Northern red oak, sugar maple, Eastern hemlock, white pine, mountain laurel			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Cobble, roots along bank, debris pile			
Aquatic Organisms Observed <i>(list)</i> : Mayfly, caddis fly, stonefly			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Logging road, no culvert			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>3</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA426

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Moderate sinuosity, weak to moderate riffle pool, strong grade control, moderate bars and benches, debris piles.

saua426 previously named saub111

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA426 facing southwest upstream



Waterbody SAUA426 facing northwest across





Waterbody SAUA426 facing northeast downstream



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Buckhorn Creek	
Waterbody ID: SAUA424		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: 01-03			
Tract Number(s): 07-001- AR466		Nearest Milepost: 120.2	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>20.0</u> ft.		OHWM Indicator: <i>(check all that apply)</i>	
OHWM Height: <u>3.0</u> ft.		<input checked="" type="checkbox"/> Clear line on bank <input checked="" type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: <u>27</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>10.0</u> ft.	Width of Waterbody - Water Edge to Water Edge: <u>15.0</u> ft.	Depth of Water: <i>(Approx.)</i> <u>1.0</u> ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> <u>2.0</u> fps	Bank height Right: <u>6</u> ft. Left: <u>5</u> ft.
N/A <input type="checkbox"/>		Bank slope Right: <u>85</u> degrees Left: <u>88</u> degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i>			
% of Substrate:      _____% <u>10</u> % <u>40</u> % <u>40</u> % <u>5</u> % <u>5</u> %      _____%      _____%			
Width of Riparian Zone: <u>125</u> ft.		Vegetative Layers: <i>(check all that apply)</i>	
N/A <input type="checkbox"/>		<input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input type="checkbox"/> Herbs	
Avg. DBH of Dominants: <i>(approx.)</i>		<u>10</u> in. <u>2</u> in.	
Dominant Bank Vegetation <i>(list)</i> : Northern red oak, sugar maple, chestnut oak, white pine, mountain laurel			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Cobble, roots along bank, debris pile			
Aquatic Organisms Observed <i>(list)</i> : Mayfly, caddis fly, stonefly			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Forest service road along left bank			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>3</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA424

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Moderate sinuosity, weak to moderate riffle pool, strong grade control, strong bars and benches, debris piles.

saua424 previously named saub113

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA424 facing north upstream



Waterbody SAUA424 facing west across





Waterbody SAUA424 facing south downstream



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Buckhorn Creek	
Waterbody ID: SAUA425		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: 01-03			
Tract Number(s): 07-001- AR466A		Nearest Milepost: 120.2	Associated Wetland ID(s): none
Survey Type: <i>(check one)</i> <input type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 1.0 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.2 ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: 2 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 0.5 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> 0 ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> 0 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> ____ fps N/A <input checked="" type="checkbox"/>	Bank height Right: 2 ft. Left: 2 ft.	Bank slope Right: 85 degrees Left: 85 degrees
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____%      10%      30%      10%      50%      _____%      _____%			
Width of Riparian Zone: ____ ft. N/A <input checked="" type="checkbox"/>		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> 6 in.      2 in.	
Dominant Bank Vegetation <i>(list)</i> : Northern red oak, sugar maple, white oak, mountain laurel			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): none			
Aquatic Organisms Observed <i>(list)</i> : none			
T&E Species Observed <i>(list)</i> : none			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): Logging road, no culvert, timbered			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>3</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA425

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Weak sinuosity, leaf litter and fibrous roots present in channel, weak to absent ordinary high water mark, lacked hydric soils.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA425 facing north upstream



Waterbody SAUA425 facing east across





Waterbody SAUA425 facing south downstream



# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Buckhorn Creek		Waterbody ID: SAUA428
Date: 9/23/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: SAUA428_001-003
Tract Number(s): 07-001		Nearest Milepost: 120.4	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: <u>15</u> ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
OHWM Height: <u>3</u> ft.		<input checked="" type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: <u>25</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>6</u> ft.	Width of Waterbody - Water Edge to Water Edge: <u>10</u> ft.	Depth of Water: <i>(Approx.)</i> <u>1</u> ft.	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> <u>1</u> fps	Bank height Right: <u>5</u> ft. Left: <u>6</u> ft.	Bank slope Right: <u>40</u> degrees Left: <u>90</u> degrees	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input checked="" type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _____% <u>10</u> % <u>50</u> % <u>35</u> % <u>5</u> %      _____%      _____%      _____%				
Width of Riparian Zone: <u>100</u> ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs			
N/A <input type="checkbox"/>	Avg. DBH of Dominants: <i>(approx.)</i> <u>14</u> in. <u>2</u> in.			
Dominant Bank Vegetation <i>(list)</i> : Red Oak, White Pine, American Hornbeam, Striped Maple, Violet, Christmas fern, multiflora rose, wintergreen				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Deep pools and riffles, over hanging banks and roots, downed logs in stream bed				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA428

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream located in natural valley

saua428 previously named sauc008

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA428 facing north upstream



Waterbody SAUA428 facing south downstream



Waterbody SAUA428 facing east across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Stoutameyer Branch	
Waterbody ID: SAUA429		Date: 9/23/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: SAUA429_001-003			
Tract Number(s): 07-001		Nearest Milepost: 120.55	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>  3  </u> ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
Height: <u>  0.5  </u> ft.		<input checked="" type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: <u>  10  </u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>  1  </u> ft.	Width of Waterbody - Water Edge to Water Edge: <u>  1  </u> ft.	Depth of Water: <i>(Approx.)</i> <u>  0.2  </u> ft.
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> <u>  0.5  </u> fps	
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>	
Bank height Right: <u>  3  </u> ft. Left: <u>  4  </u> ft.		Bank slope Right: <u>  50  </u> degrees Left: <u>  50  </u> degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input checked="" type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____%      _____%      _____% <u>  5  </u> % <u> 20  </u> % <u> 75  </u> %      _____%      _____%			
Width of Riparian Zone: <u>  </u> ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs	
N/A <input checked="" type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> <u>  8  </u> in. <u>  2  </u> in.	
Dominant Bank Vegetation <i>(list)</i> : White Oak, Chestnut Oak, Red Maple, American Hornbeam			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): None			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA429

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream located in a drainage way

saua429 previously name sauc009

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA429 facing north upstream



Waterbody SAUA429 facing south downstream



Waterbody SAUA429 facing east across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Jennings Branch	
Waterbody ID: SAUA421		Date: 9/20/2016	
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: CR, SA
Photos: SAUA421_001-003			
Tract Number(s): 07-001		Nearest Milepost: 122.45	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: _ 3 _ ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
Height: _ 0.5 _ ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
N/A <input type="checkbox"/>			
Width of Waterbody - Top of Bank to Top of Bank: _ 15 _ ft.	Width of Waterbody - Toe of Slope to Toe of Slope: _ 1 _ ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> _ 2 _ ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> _ 0.3 _ ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _ 0.5 _ fps N/A <input type="checkbox"/>	Bank height Right: _ 4 _ ft. Left: _ 3 _ ft.	Bank slope Right: _ 50 _ degrees Left: _ 30 _ degrees
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:			
% of Substrate:      _____ %      _____ %      _____ % <u>30</u> % <u>70</u> %      _____ %      _____ %      _____ %			
Width of Riparian Zone: _____ ft. N/A <input checked="" type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
Avg. DBH of Dominants: <i>(approx.)</i> <u>14</u> in. <u>2</u> in.			
Dominant Bank Vegetation <i>(list)</i> : White pine, mountain laurel, common smilax, dogwood, sphagnum			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

SAUA421

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream loses bed in some sections when the stream goes underground

saua421 previously named sauc010

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA421 facing northeast upstream



Waterbody SAUA421 facing southwest downstream





Waterbody SAUA421 facing east across



# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Jennings Branch		Waterbody ID: SAUA422
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: SAUA422_001-003
Tract Number(s): 07-001		Nearest Milepost: 118.1	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: _ 4 _ ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
Height: _ 0.8 _ ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: _ 15 _ ft.	Width of Waterbody - Toe of Slope to Toe of Slope: _ 2 _ ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> _ 3 _ ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> _ 0.5 _ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _ 1 _ fps N/A <input type="checkbox"/>	Bank height Right: _ 3 _ ft. Left: _ 4 _ ft.	Bank slope Right: _ 30 _ degrees Left: _ 70 _ degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Bedrock <input type="checkbox"/> Boulder <input checked="" type="checkbox"/> Cobble <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Silt/ clay <input type="checkbox"/> Organic <input type="checkbox"/> Other:				
% of Substrate:      _ 5 _ %      _____ %      _ 20 _ %      _ 55 _ %      _ 20 _ %      _____ %      _____ %      _____ %				
Width of Riparian Zone: _ 10 _ ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs			
Avg. DBH of Dominants: <i>(approx.)</i> _ 12 _ in.      _ 2 _ in.				
Dominant Bank Vegetation <i>(list)</i> : White pine, mountain laurel, chestnut oak, scarlet oak, lowbush blueberry, pasture rose				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, downed logs, overhanging roots				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA422

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.


**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

saua422 previously named sauc011

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA422 facing east upstream



Waterbody SAUA422 facing west downstream





Waterbody SAUA422 facing south across



# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Jennings Branch		Waterbody ID: SAUA423
Date: 9/20/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: SAUA423_001-003
Tract Number(s): 07-001		Nearest Milepost: 123.0	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: <u>  3  </u> ft.  Height: <u>  0.5  </u> ft. N/A <input type="checkbox"/>		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining  <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
Width of Waterbody - Top of Bank to Top of Bank: <u>  8  </u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>  1  </u> ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input type="checkbox"/> <u>  2  </u> ft.	Depth of Water: <i>(Approx.)</i> N/A <input type="checkbox"/> <u>  0.2  </u> ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> <u>  0.3  </u> fps N/A <input type="checkbox"/>	Bank height Right: <u>  3  </u> ft. Left: <u>  5  </u> ft.	Bank slope Right: <u>  40  </u> degrees Left: <u>  60  </u> degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> % of Substrate: <u>      </u> % <u>  10  </u> % <u>      </u> % <u>  0  </u> % <u>  20  </u> % <u>  70  </u> % <u>      </u> % <u>      </u> %				
Width of Riparian Zone: N/A <input checked="" type="checkbox"/> <u>      </u> ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> <u>  22  </u> in. <u>  2  </u> in.			
Dominant Bank Vegetation <i>(list)</i> : Red oak, post oak, blackberry, red maple, common blue violet				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

SAUA423

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Stream loses bed in some sections when the stream goes underground

saua423 was previously named sauc012

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA423 facing southeast upstream



Waterbody SAUA423 facing northwest downstream





Waterbody SAUA423 facing southwest across



# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek		Waterbody ID: saua072
State: Virginia		County: Augusta	Company: NRG	Crew Member Initials: GB, SA
Tract Number(s): 07-001.AR1		Nearest Milepost: 154.2		Photos: 3 photos
Associated Wetland ID(s): none				
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 3.0 ft.		OHWM Indicator: <i>(check all that apply)</i>		
Height: 0.50 ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 10.0 ft.		Width of Waterbody - Toe of Slope to Toe of Slope: 2.5 ft.		Depth of Water: <i>(Approx.)</i> 0.20 ft.
		N/A <input type="checkbox"/>		N/A <input type="checkbox"/>
Sinuosity: <i>(check one)</i> <input checked="" type="checkbox"/> Straight <input type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.25 fps		Bank slope Right: 65 degrees Left: 50 degrees
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Analysis of Bank Stability and Soil Erosion Potential (i.e. root structure, vegetation, substrate characteristics): No bank instability observed, banks not well developed in certain areas.				
Analysis of Above Bank Steep Slope Stability: Slopes are variable, ranging from gentle to moderate (10-30%); no signs of instability observed.				
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other: _____				
Water Quality: Total Dissolved Solids (TDS): 10.0 mg/L      Turbidity: 1.97 NTU      Nitrogen: 0.00 mg/L      Phosphorous: 0.02 mg/L Conductivity: 11.3 µS/cm      Temperature: 8.31 °C      Dissolved Oxygen (D.O.): 10.29 mg/L      pH: 6.15				
Last Rain Event: <i>(check one)</i> <input checked="" type="checkbox"/> Over 48 hours ago <input type="checkbox"/> Within Last 48 hours <input type="checkbox"/> Within Last 24 hours <input type="checkbox"/> Currently raining				
Width of Riparian Zone: _____ ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input checked="" type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> 10.0 in.      1.0 in.		
Dominant Bank Vegetation <i>(list)</i> : Yellow poplar, chestnut oak, black cherry, northern red oak, dogwood, mountain laurel, huckleberry, greenbrier, Christmas fern				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf packs, small pools, woody debris				
Aquatic Organisms Observed <i>(list)</i> : none				
T&E Species Observed <i>(list)</i> : none				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				

Waterbody ID:

saua072

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Stream Quality<sup>a</sup>:

(check one)

High


Moderate

Low

**Notes:**

Stream begins at small head cut within a draw near centerline where subterranean flow comes to surface, downstream continues out of corridor, flow is subterranean in places along mapped course.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA072 facing south upstream



Waterbody SAUA072 facing north downstream





Waterbody SAUA072 facing east across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek	
Waterbody ID: Saua434		Date: 9/24/2016	
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS
Photos: 1-3			
Tract Number(s): 07-001.AR		Nearest Milepost: 155.45	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 8 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 1 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 12 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 2 ft.	Width of Waterbody - Water Edge to Water Edge: 5 ft.	Depth of Water: <i>(Approx.)</i> 0.5 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.2 fps	Bank height Right: 5 ft. Left: 2 ft.
N/A <input type="checkbox"/>		Bank slope Right: 90 degrees Left: 60 degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i>			
% of Substrate:      _____%      5%      40%      35%      10%      5%      5%      _____%			
Width of Riparian Zone: 50 ft.	Vegetative Layers: <i>(check all that apply)</i>		
N/A <input type="checkbox"/>	<input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
Avg. DBH of Dominants: <i>(approx.)</i> 12 in.      2 in.			
Dominant Bank Vegetation <i>(list)</i> : Red oak, witch hazel, tulip-tree, falsenettle, Japanese stiltgrass			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf Packs, overhanging banks/roots, downed coarse woody debris, pools			
Aquatic Organisms Observed <i>(list)</i> : Crayfish, minnows, frogs, caddisfly larvae, stonefly nymphs			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input checked="" type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

Saua434

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Intermittent stream mapped on NHD. Stream is strongly intermittent with deep pools with minnows in them. Fringe wetland present for part of the stream.

saua434 was previously named sauc104

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA434 facing northeast upstream



Waterbody SAUA434 facing southwest downstream





Waterbody SAUA434 facing northwest across



# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek		Waterbody ID: saua071
State: Virginia		County: Augusta	Company: NRG	Crew Member Initials: GB, SA
Tract Number(s): 07-001.AR		Nearest Milepost: 154.5		Photos: 3 photos
Associated Wetland ID(s): none				
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 3.0 ft.		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input checked="" type="checkbox"/> Scouring <input type="checkbox"/> Water staining		
OHWM Height: 0.75 ft.		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 10.0 ft.		Width of Waterbody - Toe of Slope to Toe of Slope: 2.0 ft.		Depth of Water: <i>(Approx.)</i> 0.40 ft.
		N/A <input type="checkbox"/> 2.5 ft.		N/A <input type="checkbox"/>
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 1.0 fps		Bank slope Right: 75 degrees Left: 45 degrees
N/A <input type="checkbox"/>		N/A <input type="checkbox"/>		
Analysis of Bank Stability and Soil Erosion Potential (i.e. root structure, vegetation, substrate characteristics): Banks appear stable, little exposed roots or soil, litter layer nearly continuous				
Analysis of Above Bank Steep Slope Stability: Slopes above banks appear stable, gentle to moderate (10-25%)				
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other: _____				
Water Quality: Total Dissolved Solids (TDS): 9.0 mg/L    Turbidity: 0.32 NTU    Nitrogen: 0.0 mg/L    Phosphorous: 0.03 mg/L Conductivity: 8.6 µS/cm    Temperature: 5.65 °C    Dissolved Oxygen (D.O): 11.4 mg/L    pH: 6.91				
Last Rain Event: <i>(check one)</i> <input checked="" type="checkbox"/> Over 48 hours ago <input type="checkbox"/> Within Last 48 hours <input type="checkbox"/> Within Last 24 hours <input type="checkbox"/> Currently raining				
Width of Riparian Zone: 30 ft.		Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
N/A <input type="checkbox"/>		Avg. DBH of Dominants: <i>(approx.)</i> 10.0 in.    0.75 in.		
Dominant Bank Vegetation <i>(list)</i> : White oak, red oak, chestnut oak, sweet birch, dogwood, mountain laurel, Christmas fern				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Small pools, leaf packs				
Aquatic Organisms Observed <i>(list)</i> : invertebrates				
T&E Species Observed <i>(list)</i> : none				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None apparent				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				

Waterbody ID:  
saua071

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

Stream Quality<sup>a</sup>:  
(check one)

High


Moderate

Low

**Notes:**

Upstream continues out of corridor, loses bed/bank/OHWM near western edge of corridor in a rocky flat where flow becomes subterranean.

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA071 facing east upstream



Waterbody SAUA071 facing west downstream





Waterbody SAUA071 facing north across

# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek	
Waterbody ID: Saua433		Date: 9/24/2016	
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, AS
Photos: 1-3			
Tract Number(s): 07-001.AR		Nearest Milepost: 120.2	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: <u>10</u> ft.  Height: <u>0.5</u> ft. N/A <input type="checkbox"/>		OHWM Indicator: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input checked="" type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: <u>14</u> ft.	Width of Waterbody - Toe of Slope to Toe of Slope: <u>2</u> ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> ___ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> ___ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> ___fps N/A <input checked="" type="checkbox"/>	Bank height Right: <u>3.5</u> ft. Left: <u>3.5</u> ft.	Bank slope Right: <u>70</u> degrees Left: <u>60</u> degrees
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i> % of Substrate:      ___% <u>10</u> % <u>45</u> % <u>35</u> % <u>5</u> %      ___% <u>5</u> %      ___%			
Width of Riparian Zone: <u>n/a</u> ft. N/A <input type="checkbox"/>	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> <u>12</u> in. <u>2</u> in.		
Dominant Bank Vegetation <i>(list)</i> : Red maple, white pine, American beech, chestnut oak, red oak, Spicebush, common greenbrier			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf Packs, overhanging banks, downed coarse woody debris, pools			
Aquatic Organisms Observed <i>(list)</i> : None			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

Saua433

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

intermittent stream mapped on NHD

saua433 was previously named sauc103

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA433 facing southeast upstream



Waterbody SAUA433 facing northwest downstream





Waterbody SAUA433 facing northeast across

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek		Waterbody ID: Saua432
Date: 9/24/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: 1-3
Tract Number(s): 07-001.AR		Nearest Milepost: 155	Associated Wetland ID(s): None	
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 4 ft.		OHWM Indicator: <i>(check all that apply)</i>		
Height: 0.3 ft.		<input type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 10 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> _____ ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> _____ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _____ fps N/A <input checked="" type="checkbox"/>	Bank height Right: 1.5 ft. Left: 2.5 ft.	Bank slope Right: 70 degrees Left: 70 degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____%      20%      70%      10%      _____%      _____%      _____%				
Width of Riparian Zone: N/A <input checked="" type="checkbox"/> _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> 12 in.      2 in.			
Dominant Bank Vegetation <i>(list)</i> : American beech, red oak, red maple, American hog peanut, witch hazel, cucumber tree, common greenbrier, hackberry				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf Packs				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				

Waterbody ID:

Saua432

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.

**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Channel may be weakly ephemeral. There are a few FACU plants growing in the bed of the channel, numerous fibrous roots, and leaf piles found throughout the stream.

sau102 previously named sau432

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA432 facing east upstream



Waterbody SAUA432 facing west downstream



Waterbody SAUA432 facing south across



# Linear Waterbody Data Sheet

Survey Description			
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek	
Waterbody ID: Saua431		Date: 9/24/2016	
State: Virginia	County: Augusta	Company: NRG	Crew Member Initials: GB, AS
Photos: 1-3			
Tract Number(s): 07-001.AR		Nearest Milepost: 155	Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:			
Physical Attributes			
Stream Classification: <i>(check one)</i> <input type="checkbox"/> Ephemeral <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Perennial			
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:			
OHWM Width: 2 ft.		OHWM Indicator: <i>(check all that apply)</i>	
Height: 0.3 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining	
N/A <input type="checkbox"/>		<input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change	
Width of Waterbody - Top of Bank to Top of Bank: 8 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1 ft.	Width of Waterbody - Water Edge to Water Edge: 1 ft.	Depth of Water: <i>(Approx.)</i> 0.05 ft.
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering		Water velocity: <i>(Approx.)</i> 0.2 fps	Bank height Right: 2 ft. Left: 2.5 ft.
N/A <input type="checkbox"/>		Bank slope Right: 50 degrees Left: 70 degrees	
Qualitative Attributes			
Water Appearance: <i>(check one)</i> <input type="checkbox"/> No water <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:			
Substrate: <i>(check all that apply)</i>			
% of Substrate:      _____%      _____%      5%      70%      15%      _____%      10%      _____%			
Width of Riparian Zone: n/a ft.	Vegetative Layers: <i>(check all that apply)</i>		
N/A <input type="checkbox"/>	<input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs		
Avg. DBH of Dominants: <i>(approx.)</i> 14 in.      2 in.			
Dominant Bank Vegetation <i>(list)</i> : Tulip-tree, American beech, red oak, red maple, common greenbrier, sassafras			
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf Packs, overhanging banks			
Aquatic Organisms Observed <i>(list)</i> : Caddisfly larvae, stonefly nymph			
T&E Species Observed <i>(list)</i> : None			
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None			
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated			
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Waterbody ID:

Saua431

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Seep fed intermittent stream

saua431 previously named sauc101

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)







Waterbody SAUA431 facing southeast upstream



Waterbody SAUA431 facing northwest downstream





Waterbody SAUA431 facing southwest across

# Linear Waterbody Data Sheet

Survey Description				
Project Name: Atlantic Coast Pipeline		Waterbody Name: UNT to Back Creek		Waterbody ID: Saua430
Date: 9/24/2016				
State: Virginia	County: Augusta	Company: ERM	Crew Member Initials: GB, AS	Photos: 1-3
Tract Number(s): 07-001.AR; 07-058-E049		Nearest Milepost: 155.1		Associated Wetland ID(s): None
Survey Type: <i>(check one)</i> <input checked="" type="checkbox"/> Centerline <input type="checkbox"/> Re-Route <input type="checkbox"/> Access Road <input type="checkbox"/> Other:				
Physical Attributes				
Stream Classification: <i>(check one)</i> <input checked="" type="checkbox"/> Ephemeral <input type="checkbox"/> Intermittent <input type="checkbox"/> Perennial				
Waterbody Type: <i>(check one)</i> <input type="checkbox"/> River <input checked="" type="checkbox"/> Stream <input type="checkbox"/> Ditch <input type="checkbox"/> Canal <input type="checkbox"/> Other:				
OHWM Width: 4 ft.		OHWM Indicator: <i>(check all that apply)</i>		
Height: 0.3 ft.		<input checked="" type="checkbox"/> Clear line on bank <input type="checkbox"/> Shelving <input type="checkbox"/> Wrested vegetation <input type="checkbox"/> Scouring <input type="checkbox"/> Water staining <input type="checkbox"/> Bent, matted, or missing vegetation <input type="checkbox"/> Wrack line <input checked="" type="checkbox"/> Litter and debris <input type="checkbox"/> Abrupt plant community change <input type="checkbox"/> Soil characteristic change		
N/A <input type="checkbox"/>				
Width of Waterbody - Top of Bank to Top of Bank: 8 ft.	Width of Waterbody - Toe of Slope to Toe of Slope: 1 ft.	Width of Waterbody - Water Edge to Water Edge: N/A <input checked="" type="checkbox"/> _____ ft.	Depth of Water: <i>(Approx.)</i> N/A <input checked="" type="checkbox"/> _____ ft.	
Sinuosity: <i>(check one)</i> <input type="checkbox"/> Straight <input checked="" type="checkbox"/> Meandering	Water velocity: <i>(Approx.)</i> _____ fps N/A <input checked="" type="checkbox"/>	Bank height Right: 1.5 ft. Left: 1.5 ft.	Bank slope Right: 70 degrees Left: 70 degrees	
Qualitative Attributes				
Water Appearance: <i>(check one)</i> <input checked="" type="checkbox"/> No water <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Sheen on surface <input type="checkbox"/> Surface scum <input type="checkbox"/> Algal mats <input type="checkbox"/> Other:				
Substrate: <i>(check all that apply)</i> % of Substrate:      _____%      _____%      15%      75%      10%      _____%      _____%      _____%				
Width of Riparian Zone: N/A <input checked="" type="checkbox"/> _____ ft.	Vegetative Layers: <i>(check all that apply)</i> <input checked="" type="checkbox"/> Trees: <input checked="" type="checkbox"/> Saplings/Shrubs: <input checked="" type="checkbox"/> Herbs Avg. DBH of Dominants: <i>(approx.)</i> 12 in.      2 in.			
Dominant Bank Vegetation <i>(list)</i> : Tulip-tree, American beech, red oak, red maple, Japanese stiltgrass, American hog peanut				
Aquatic Habitats (ex: submerged or emerged aquatic vegetation, overhanging banks/roots, leaf packs, large submerged wood, riffles, deep pools): Leaf Packs				
Aquatic Organisms Observed <i>(list)</i> : None				
T&E Species Observed <i>(list)</i> : None				
Disturbances (ex: livestock access, manure in waterbody, waste discharge pipes): None				
Tributary is: <i>(check one)</i> <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Artificial, man-made <input type="checkbox"/> Manipulated				
Stream Quality <sup>a</sup> : <i>(check one)</i> <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low				



Waterbody ID:

saua430

<sup>a</sup> **High Quality:** Natural channel, natural vegetation extends at least one or two active channel widths on each side; banks stable and protected by roots; water color is clear to tea-colored; no barriers to fish movement; many fish cover types available; diverse and stable aquatic habitat; no disturbance by livestock or man.

**Moderate Quality:** Altered channel evidenced by rip-rap; natural vegetation extends 1/3-1/2 of the active channel width on each side; filtering function or riparian vegetation only moderately compromised; banks moderately unstable; water color is cloudy, submerged objects covered with greenish film; moderate odor; minor barriers to fish movement; fair aquatic habitat; minimum disturbance by livestock or man.


**Low Quality:** Channel is actively down cutting or widening; rip rap and channelization excessive; natural vegetation less than 1/3 of the active channel width on each side; lack of regeneration; filtering function severely compromised; banks unstable (eroding); water color is muddy and turbid; obvious pollutants (algal mats, surface scum, surface sheen); heavy odor; severe barriers to fish movement; little to no aquatic habitat; severe disturbance from livestock or man.

**Notes:**

Channel may be weakly ephemeral. There are a few FACU plants growing in the bed of the channel, numerous fibrous roots, and leaf piles found throughout the stream

saua430 previously named sauc100

**Waterbody Sketch** (Include north arrow, centerline, distance from centerline, data point location, survey boundary, and IDs of associated features)





Waterbody SAUA430 facing east upstream



Waterbody SAUA430 facing west downstream





Waterbody SAUA430 facing north across